





General information

Make	NISSAN
Model	370 Z V6 GT
Colour	Silver
Year of manufacture	2010
Top speed	155 mph
0 - 60 mph	5.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	328 BHP
Max. torque	363 Nm at 5.200 rpm
Engine capacity	3.696 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	36.2 mpg
Consumption combined	26.9 mpg
CO2 emission	247 g/km
CO2 label	L







Internet history	
Entry 2	
Date	2022-11-14
Pictures	0
Listing price	View report

source: carcraft.co.uk

Entry 1

Date	2022-01-18
Pictures	10
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-19
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	27
Total items failed	0

MOT #14		2023-12-19 10:07
MOT test	number	481737859264
Result		✓ Passed
Next expi	ry date	2024-12-19
Advice	Offside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge on 1.6mm (5.2.3 (e))	

MOT #13	2023-12-14 12:48
MOT test number	853057698748
Result	🗙 Failed
Advice Offside Rear Tyre worn close to legal limit/worn on edge on 2mm (5.2.3 (e))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge on 1.6mm (5.2.3 (e))	
MAJOR Windscreen washer not working (3.5 (a))	

MOT #12	2022-12-20 14:21
MOT test number	374705171647
Result	✓ Passed





MOT #11		2022-04-08 14:41
MOT test	number	791624421341
Result		✓ Passed
Advice	Rear Subframe mounting prescribed area is corroded but not considered exces	sive (5.3.6 (a) (i))
Minor	Front Headlamp lens slightly defective both (4.1.1 (b) (i))	
Advice	Front Brake hose has slight corrosion to ferrule both (1.1.12 (f) (i))	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Front Outer Brake pipe corroded, covered in grease or other material both (1.1	.11 (c))
Advice	Rear Brake hose has slight corrosion to ferrule both (1.1.12 (f) (i))	

MOT #10		2021-03-26 14:28
MOT test	number	135970033030
Result		✓ Passed
Advice	Rear Brake hose has slight corrosion to ferrule both (1.1.12 (f) (i))	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Front Brake hose has slight corrosion to ferrule both (1.1.12 (f) (i))	
Advice	Front Brake pipe corroded, covered in grease or other material both (1.1.11 (c))	
Advice	Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	

MOT #9		2020-03-13 14:17
MOT test	number	412725486128
Result		✓ Passed
Advice	Rear Brake hose has slight corrosion to ferrule both (1.1.12 (f) (i))	
Advice	Front Brake hose has slight corrosion to ferrule both $(1.1.12 (f) (i))$	





MOT #8		2019-04-11 13:37
MOT test numbe	er	729145890571
Result		✓ Passed
MOT #7		2019-04-05 08:55
MOT test numbe	er	958756561606
Result		🗙 Failed
DANGEROUS	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
DANGEROUS	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
DANGEROUS	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
DANGEROUS	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #6	2018-09-13 10:44
MOT test number	848150652797
Result	✓ Passed

MOT #5	2017-07-12 11:23
MOT test number	532721908489
Result	✓ Passed

MOT #4	2016-07-13 11:28
MOT test number	481570234958
Result	✓ Passed
Advice Under trays fitted	

MOT #3	2015-04-15 11:05
MOT test number	517885005199
Result	✓ Passed





MOT #2		2014-04-10 15:19
MOT test	number	246560904497
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	

MOT #1		2013-04-05 12:38
MOT test	number	248675293022
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Notice	Under-trays fitted obscuring some underside components	





Tax & MOT check

✓ Taxed	√ МОТ
Tax due: 1 June 2024	Expires: 19 December 2024
Tax status	Valid until 1 June
Days left	34
MOT expiry date	19 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		4. AMP
Туре		
Damage 2		XAMPL
Date	E C	
Category		amer
Туре		

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-01-21
Last registration	2023-12-19
Complete history	See info



Registration #1	2010-01-21	25 mi
Registration #2	2013-04-05	25.102 mi
Registration #3	2014-04-10	38.179 mi
Registration #4	2015-04-15	49.122 mi
Registration #5	2016-07-13	56.562 mi
Registration #6	2017-07-12	60.361 mi
Registration #7	2018-09-13	65.675 mi
Registration #8	2019-04-05	68.491 mi
Registration #9	2019-04-11	68.491 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		10.200 au





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	1845 mm
Height	1315 mm
Length	4250 mm
Wheel base	2550 mm
Kerb weight	1508 kg
Max. allowed weight	1800 kg

Additional information

Fuel tank capacity	72
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	2
Number of axles	2
Engine number	140426