



report date: 2024-03-29

General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Grey
Year of manufacture	2009
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 2

Date	2022-02-22
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2022-01-25
Pictures	12
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-22
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	37
Total items failed	11

MOT #16	2024-02-23 17:18
---------	------------------

MOT test number	574610533514
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-02-22
------------------	------------

- Advice** Offside Front Macpherson strut mounting corroded but not seriously weakened top mount (5.3.3 (b) (i))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Macpherson strut mounting corroded but not seriously weakened top mount (5.3.3 (b) (i))
- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #15**

2024-02-19 17:44

MOT test number

312606758220

Result**✗ Failed**

Advice Nearside Front Macpherson strut mounting corroded but not seriously weakened top mount (5.3.3 (b) (i))

Fail Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Offside Front Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Macpherson strut mounting corroded but not seriously weakened top mount (5.3.3 (b) (i))

Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both not working (4.7.1 (b) (ii))

Advice Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #14

2023-01-16 13:36

MOT test number

591132771420

Result**✓ Passed****MOT #13**

2022-01-12 18:21

MOT test number

435808808169

Result**✓ Passed****MOT #12**

2020-03-16 16:54

MOT test number

279503823991

Result**✓ Passed**

Advice Rear bumper damaged

Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside door handle damaged/insecure

**MOT #11**

2020-03-14 10:26

MOT test number

232310446135

Result**✗ Failed****Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Rear bumper damaged**Fail** Offside Front Road wheel badly distorted (5.2.2 (c) (i))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside door handle damaged/insecure**Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #10**

2019-03-13 12:11

MOT test number

480586033223

Result**✓ Passed****Advice** Items removed from driver's view prior to test phone holder**Advice** Drivers door handle broken but still operating**MOT #9**

2019-03-13 10:18

MOT test number

346158921139

Result**✗ Failed****Advice** Items removed from driver's view prior to test phone holder**Advice** Nearside Front tyre worn on edge**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Drivers door handle broken but still operating**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #8**

2018-03-07 16:56

MOT test number

714096840098

Result

✓ Passed

Advice Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Advice Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #7

2018-03-07 16:56

MOT test number

985747324704

Result

✗ Failed

Advice Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Pass with rectification Nearside Front position lamp(s) obscured more than 50% (1.1.A.3c)

Pass with rectification Nearside Headlamp aim too high (1.8)

Advice Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Pass with rectification Offside Front position lamp(s) obscured more than 50% (1.1.A.3c)

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #6

2017-03-11 11:37

MOT test number

463991769042

Result

✓ Passed

Advice Nearside Rear tyre badly worn and cracked at outer edge

Advice Unable to properly check rear seat belts due to contents in rear of vehicle

MOT #5

2016-03-15 13:11

MOT test number

703889008359

Result

✓ Passed

**MOT #4** 2016-03-15 13:11**MOT test number** 803828240779**Result** ✗ Failed**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2015-01-31 09:43**MOT test number** 899501035048**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-08-29 13:56**MOT test number** 818461643234**Result** ✓ Passed**MOT #1** 2013-03-04 16:58**MOT test number** 347913163094**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
22 February 2025

Tax status	Valid until 1 August
Days left	93
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-11-10
Last registration	2024-02-23
Complete history	See info



Registration #1	2009-11-10	13 mi
Registration #2	2013-03-04	6.949 mi
Registration #3	2013-08-29	6.958 mi
Registration #4	2015-01-31	17.712 mi
Registration #5	2016-03-15	22.881 mi
Registration #6	2016-03-15	22.881 mi
Registration #7	2017-03-11	42.935 mi
Registration #8	2018-03-07	51.784 mi
Registration #9	2018-03-07	51.784 mi
Registration #10	2019-03-13	64.610 mi
Registration #11	2019-03-20	75.377 mi
Registration #12	2019-03-20	75.377 mi
Registration #13	2019-03-20	75.377 mi
Registration #14	2019-03-20	75.377 mi
Registration #15	2019-03-20	75.377 mi
Registration #16	2019-03-20	75.377 mi
Registration #17	2019-03-20	75.377 mi
Registration #18	2019-03-20	75.377 mi
Registration #19	2019-03-20	75.377 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	107462