



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO POP
Colour	White
Year of manufacture	2013
Top speed	97 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg
CO2 emission	126 g/km
CO2 label	D





Internet history

Entry 2

Date	2022-11-19
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-04-15
Pictures	19
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-03
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	25
Total items failed	7

MOT #12 2023-06-21 13:44

MOT test number 339289708434

Result ✓ Passed

Next expiry date 2024-07-03

Advice Front and rear sub-frame badly rusted/corroded+front +rear suspensions components badly rusted

Advice Offside Rear Tyre slightly damaged/cracking or perishing tyre tread has a serious deep cracks (strong advice) (5.2.3 (d) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Exhaust system +rear silencer box badly corroded

MOT #11 2022-07-04 16:07

MOT test number 837239205450

Result ✓ Passed

MOT #10 2022-04-20 14:09

MOT test number 153140546412

Result ✓ Passed

**MOT #9** 2021-11-03 09:37**MOT test number** 782334616415**Result** ✓ Passed**Advice** Exhaust slightly corroded**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2021-11-02 13:33**MOT test number** 414365130847**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Exhaust slightly corroded**MOT #7** 2020-11-06 10:42**MOT test number** 788547076750**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Exhaust slightly corroded**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Brake disc worn, but not excessively both front (1.1.14 (a) (i))**Advice** Wheel trims fitted

**MOT #6** 2019-05-14 13:33**MOT test number** 215610919640**Result** ✓ Passed**Advice** Exhaust mounting defective exhaust to gearbox (6.1.2 (a))**Advice** Coolant leak on radiator**MOT #5** 2019-05-13 13:21**MOT test number** 802199928772**Result** ✗ Failed**Fail** Nearside Rear Position lamp not working (4.2.1 (a))**Advice** Handbrake travel**Advice** Coolant leak on radiator**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking or perishing (5.2.3 (d) (ii))**Advice** Exhaust mounting defective exhaust to gearbox (6.1.2 (a))**Advice** Engine oil level low**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking or perishing (5.2.3 (d) (ii))**MOT #4** 2018-05-16 10:15**MOT test number** 988828208713**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2018-05-16 10:15
MOT test number	550272361085
Result	✗ Failed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Pass with rectification	Nearside Rear position lamp(s) not working (1.1.A.3b)

MOT #2	2017-03-21 09:50
MOT test number	518343883672
Result	✓ Passed
Advice	Engine cover fitted
Advice	Wheel trims fitted

MOT #1	2016-12-03 07:58
MOT test number	833092543580
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
3 July 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	3 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-12-13
Last registration	2023-06-21
Complete history	See info



Registration #1	2013-12-13	26 mi
Registration #2	2016-12-03	25.053 mi
Registration #3	2017-03-21	26.293 mi
Registration #4	2018-05-16	29.891 mi
Registration #5	2018-05-16	29.891 mi
Registration #6	2019-05-13	35.254 mi
Registration #7	2019-05-14	35.255 mi
Registration #8	2020-11-06	42.988 mi
Registration #9	2020-11-06	42.988 mi
Registration #10	2020-11-06	42.988 mi
Registration #11	2020-11-06	42.988 mi
Registration #12	2020-11-06	42.988 mi
Registration #13	2020-11-06	42.988 mi
Registration #14	2020-11-06	42.988 mi
Registration #15	2020-11-06	42.988 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	0426917