



PXIIWAE

report date: 2024-03-28

General information

Make	CITROEN
Model	C5 HDI EXCLUSIVE
Colour	Grey
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	160 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	41.5 mpg
CO2 emission	179 g/km
CO2 label	I








Internet history

Entry 1

Date	2021-09-24
Pictures	7
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-24
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	35
Total items failed	6

MOT #13	2023-09-25 06:09
MOT test number	955493047091
Result	✓ Passed
Next expiry date	2024-09-24
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rubber bush (5.3.4 (a) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2022-09-02 08:42
MOT test number	842764417524
Result	✓ Passed
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))



MOT #11

2021-09-09 11:18

MOT test number

779316785218

Result

✓ Passed

- Advice

Rear suspension pipe ferrels rusted
- Advice

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice

Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Offside Front fluid suspension leg damp at base and assessed okay at time of test
- Advice

Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice

Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #10

2021-09-09 11:18

MOT test number

680559337747

Result

✗ Failed

- Advice

Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice

Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice

Offside Front fluid suspension leg damp at base and assessed okay at time of test
- Pass with rectification

Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Advice

Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice

Rear suspension pipe ferrels rusted

**MOT #9**

2020-09-18 15:43

MOT test number

404078473104

Result

✓ Passed

- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #8

2020-09-09 12:06

MOT test number

549717063152

Result

✗ Failed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Offside Front Power steering component leaking power steering rack top seal (2.1.5 (a))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Fail** Central Rear Brake pipe excessively corroded (1.1.11 (c))

MOT #7

2019-05-03 12:03

MOT test number

483555116482

Result

✓ Passed

- Advice** Offside front shocker has slight leak at bottom of unit

**MOT #6** 2018-05-07 09:38**MOT test number** 898694279183**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Slight wear in offside front antiroll link.**MOT #5** 2018-04-24 12:49**MOT test number** 762806381027**Result** ✗ Failed**Advice** Slight wear in offside front antiroll link.**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Fail** Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)**Fail** Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #4** 2017-05-02 08:36**MOT test number** 411008460327**Result** ✓ Passed**Advice** Tyre worn close to the legal limit Nearside front at 2mm, Offside front at 3mm. (4.1.E.1)**MOT #3** 2016-04-16 10:36**MOT test number** 447323692277**Result** ✓ Passed**Advice** Offside Front Lower Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)



MOT #2	2015-05-02 09:23
MOT test number	708582725189
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Nail in nearside front tyre
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Nail in offside rear tyre

MOT #1	2014-05-06 14:55
MOT test number	708636924117
Result	✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-03-28
Last registration	2023-09-25
Complete history	See info



Registration #1	2011-03-28	9 mi
Registration #2	2014-05-06	69.055 mi
Registration #3	2015-05-02	83.458 mi
Registration #4	2016-04-16	98.206 mi
Registration #5	2017-05-02	113.486 mi
Registration #6	2018-04-24	125.340 mi
Registration #7	2018-05-07	125.450 mi
Registration #8	2019-05-03	136.887 mi
Registration #9	2020-05-03	147.942 mi
Registration #10	2021-05-03	159.000 mi
Registration #11	2022-05-03	170.058 mi
Registration #12	2023-05-03	181.116 mi
Registration #13	2024-05-03	192.174 mi
Registration #14	2025-05-03	203.232 mi
Registration #15	2026-05-03	214.290 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	81%
Children	77%
Pedestrian	32%
Safety systems	83%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1451 mm
Length	4779 mm
Wheel base	2815 mm
Kerb weight	1609 kg
Max. allowed weight	2190 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	DYYG4009175