





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	FOX
Colour	Blue
Year of manufacture	-
Top speed	92 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	55 BHP
Max. torque	108 Nm at 3.000 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	36.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg



CarCheck.co.uk page 1/10



MOT history

MOT #15	2020-06-25 08:47
MOT test number	280988634840
Result	✓ Passed
Next expiry date	2021-06-24
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #14		2019-06-24 08:52
MOT test	number	526320985424
Result		✓ Passed
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice	Power steering pipe/hose slightly corroded (2.1.5 (g) (i))	
Advice	Rear axle corroded	

MOT #13	2019-06-21 14:41
MOT test number	921023783889
Result	× Failed
Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice Rear axle corroded	
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Power steering pipe/hose slightly corroded (2.1.5 (g) (i))	
Fail Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))	
Fail Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))	

MOT #12	2018-09-05 14:32
MOT test number	665039355435
Result	✓ Passed
Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))	

CarCheck.co.uk page 2/10



MOT test number

SY56TEJ report date: 2024-03-29

541456095676

MOT #11 2018-09-05 14:32

Result X Failed

Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))

MOT #10 2017-08-25 13:44

MOT test number 940198412936

Result \(\sqrt{Passed} \)

MOT #9 2016-09-30 06:50

MOT test number 250066013359

Result \rightarrow Passed

MOT #8 2016-09-29 10:35

MOT test number 458830923031

Result X Failed

Fail Nearside Front Brake hose excessively deteriorated (3.6.B.4d)

Fail Nearside Rear Shock absorber has a serious fluid leak (2.7.3)

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Offside Front Brake hose slightly deteriorated (3.6.B.4d)

Advice Offside Rear Shock absorber has slight corrosion to the casing (2.7.2a)

MOT #7 2015-09-25 12:46

MOT test number 534488028051

Result
✓ Passed

Advice Nearside Rear Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

CarCheck.co.uk page 3/10



MOT #6 2014-09-30 12:33

MOT test number 596553074268

Result ✓ Passed

Notice Under-trays fitted obscuring some underside components

Advice Nearside Front Lower Front suspension ball joint dust cover deteriorated, but preventing the

ingress of dirt (2.4.G.2)

Notice Nearside front wiper torn but still clearing screen

Advice Offside Front Seat belt stitching slightly frayed (5.2.2b)

MOT #5 2013-09-18 14:31

MOT test number 149371063235

Result Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2012-09-28 11:36

MOT test number 187682072203

Result ✓ Passed

MOT #3 2011-09-14 15:34

MOT test number 889707151299

Result ✓ Passed

MOT #2 2010-09-20 12:11

MOT test number 842713260227

Result ✓ Passed

MOT #1 2009-09-17 13:04

MOT test number 134880269205

Result ✓ Passed

CarCheck.co.uk page 4/10



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2

Damage 2	
Date	
Category	



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dov here.	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 7/10



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 8/10



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-09-29
Last registration	2020-06-25
Complete history	See info



Registration #1	2006-09-29	20 mi
Registration #2	2009-09-17	18.973 mi
Registration #3	2010-09-20	24.533 mi
Registration #4	2011-09-14	29.410 mi
Registration #5	2012-09-28	36.669 mi
Registration #6	2013-09-18	42.787 mi
Registration #7	2014-09-30	47.489 mi
Registration #8	2015-09-25	52.034 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		D.777 es
Registration #15		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 9/10



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	★★★★ ★
Video	see crash video



Dimensions & weight

Width	1660 mm
Height	1544 mm
Length	3828 mm
Wheel base	2465 mm
Kerb weight	1069 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	3
CarChaeleanule	naga 10/10

CarCheck.co.uk page 10/10

Number of seats	4
Number of axles	2
Engine number	BMD 255340