



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK220 CDI SPORT
Colour	Silver
Year of manufacture	2009
Top speed	137 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption


Power	148 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.1 mpg
Consumption extra urban	54.3 mpg
Consumption combined	43.5 mpg
CO2 emission	183 g/km
CO2 label	I





Internet history

Entry 1	
Date	2021-06-29
Pictures	13
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-12-05
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	15
Total items failed	4

MOT #15 2023-12-06 12:41

MOT test number 606795204344

Result ✓ Passed

Next expiry date 2024-12-05

**Advice** Nearside Brake pipe corroded, covered in grease or other material Front to rear rear section (1.1.11 (c))

**Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Offside Brake pipe corroded, covered in grease or other material Front to rear rear section (1.1.11 (c))

MOT #14 2022-12-05 15:27

MOT test number 307396042084

Result ✓ Passed

**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #13 2021-10-28 13:29

MOT test number 179589765179

Result ✓ Passed

**MOT #12** 2021-10-28 13:29**MOT test number** 896346053000**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #11** 2020-10-17 11:07**MOT test number** 964323848445**Result** ✓ Passed**MOT #10** 2019-10-05 08:35**MOT test number** 894991460260**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2018-10-23 12:37**MOT test number** 321754134259**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #8** 2018-10-19 14:46**MOT test number** 695375469288**Result** ✗ Failed

**MAJOR** Nearside Rear Brake lever not releasing correctly and functionality of brakes affected (1.1.2 (b) (ii))

**MAJOR** Nearside Rear Parking (secondary brake) on a single line braking system grabbing severely Over adjustment (1.3.1 (c))

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MAJOR** Brake pedal has insufficient reserve travel (1.1.2 (a))

**MAJOR** Offside Rear Brake lever not releasing correctly and functionality of brakes affected (1.1.2 (b) (ii))

**MAJOR** Offside Rear Parking (secondary brake) on a single line braking system grabbing severely Over adjustment (1.3.1 (c))

**MOT #7** 2017-10-11 14:07**MOT test number** 985297184478**Result** ✓ Passed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2016-10-18 14:58**MOT test number** 378506360716**Result** ✓ Passed**MOT #5** 2015-11-14 10:44**MOT test number** 588152099784**Result** ✓ Passed**MOT #4** 2014-11-19 13:48**MOT test number** 975953524319**Result** ✓ Passed



MOT #3	2013-09-06 12:05
MOT test number	428949343264
Result	✓ Passed

MOT #2	2013-09-06 11:21
MOT test number	208779443240
Result	✗ Failed
<div><div>Fail</div> Nearside Rear Tyre incorrectly seated on the wheel rim (4.1.D.1d)</div> <div><div>Fail</div> Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)</div> <div><div>Pass with rectification</div> Nearside Headlamp aim too high and too far to the right. (1.8)</div>	

MOT #1	2012-04-16 14:00
MOT test number	405037802191
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
5 December 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	5 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>Single payment (12 months)</b>	£ 320,00,-
<b>Single six month payment</b>	£ 176,00,-
<b>Total payable by 12 monthly instalments</b>	£ 336,00,-



Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-04-24
Last registration	2023-12-06
Complete history	<a href="#">See info</a>



Registration #1	2009-04-24	8 mi
Registration #2	2012-04-16	34.925 mi
Registration #3	2013-09-06	43.489 mi
Registration #4	2013-09-06	43.489 mi
Registration #5	2014-11-19	49.321 mi
Registration #6	2015-11-14	548.431 mi
Registration #7	2016-10-18	60.023 mi
Registration #8	2017-10-11	72.070 mi
Registration #9	2018-10-19	91.551 mi
Registration #10	2019-10-20	91.551 mi
Registration #11	2019-10-20	91.551 mi
Registration #12	2019-10-20	91.551 mi
Registration #13	2019-10-20	91.551 mi
Registration #14	2019-10-20	91.551 mi
Registration #15	2019-10-20	91.551 mi
Registration #16	2019-10-20	91.551 mi
Registration #17	2019-10-20	91.551 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1595 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	64696630637445