



SK59HDJ

report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | FORD |
| Model | FUSION STYLE PLUS |
| Colour | Black |
| Year of manufacture | - |
| Top speed | 101 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 79 BHP |
| Max. torque | 124 Nm at 3.500 rpm |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 33.2 mpg |
| Consumption extra urban | 53.3 mpg |
| Consumption combined | 43.5 mpg |




LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-05-31 |
| Pictures | 9 |
| Listing price | View report |



source: cargurus.co.uk

**MOT history**

| | |
|-------------------------|---|
| MOT #19 | 2024-02-06 09:35 |
| MOT test number | 723129433059 |
| Result | ✓ Passed |
| Next expiry date | 2025-02-06 |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge 195/60r15 (5.2.3 (e)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge 195/60r15 (5.2.3 (e)) |

| | |
|--------------------------------|---|
| MOT #18 | 2024-01-29 11:32 |
| MOT test number | 924916723159 |
| Result | ✗ Failed |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge 195/60r15 (5.2.3 (e)) |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge 195/60r15 (5.2.3 (e)) |
| MAJOR | Offside Rear fog lamp not working (4.5.1 (a) (ii)) |
| Pass with rectification | Offside Headlamp aim too high (4.1.2 (a)) |

| | |
|------------------------|---|
| MOT #17 | 2023-02-02 11:22 |
| MOT test number | 539585271201 |
| Result | ✓ Passed |
| Advice | Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner facing (1.1.14 (a) (ii)) |
| Advice | Offside Front Service brake fluctuating, but not excessively (1.2.1 (e)) |
| Advice | Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e)) |
| Advice | Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner facing (1.1.14 (a) (ii)) |

**MOT #16**

2023-02-02 11:02

MOT test number

374961104579

Result**✗ Failed****MAJOR** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner facing (1.1.14 (a) (ii))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner facing (1.1.14 (a) (ii))**MOT #15**

2022-01-31 13:04

MOT test number

810450095642

Result**✓ Passed****Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened Inner Face (1.1.14 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened Inner Face (1.1.14 (a) (ii))**MOT #14**

2021-01-26 16:45

MOT test number

255713322565

Result**✓ Passed****MOT #13**

2021-01-26 09:14

MOT test number

995206249004

Result**✗ Failed****MAJOR** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Offside Front Position lamp not working Side Light (4.2.1 (a) (ii))**MAJOR** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Nearside Front Upper Shock absorbers has an excessively worn bush (5.3.2 (c))

**MOT #12** 2020-01-24 12:23**MOT test number** 354146746080**Result** ✓ Passed**Advice** Items removed from driver's view prior to test sat nav and phone holder**MOT #11** 2019-02-01 12:55**MOT test number** 570942268683**Result** ✓ Passed**MOT #10** 2019-02-01 08:57**MOT test number** 619111600111**Result** ✗ Failed**MAJOR** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #9** 2018-01-25 09:53**MOT test number** 602885666740**Result** ✓ Passed**MOT #8** 2017-01-31 15:51**MOT test number** 953699528808**Result** ✓ Passed**MOT #7** 2017-01-31 09:56**MOT test number** 333547300772**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit is at 2.34mm legal limit is 1.60mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #6** 2016-01-12 14:19**MOT test number** 292216707624**Result** ✓ Passed**MOT #5** 2016-01-12 11:40**MOT test number** 431957028975**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2015-01-22 12:49**MOT test number** 527592625076**Result** ✓ Passed**MOT #3** 2014-02-07 09:44**MOT test number** 259138134073**Result** ✓ Passed**MOT #2** 2013-09-05 16:54**MOT test number** 357238943413**Result** ✓ Passed**MOT #1** 2012-10-22 08:09**MOT test number** 395546192484**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | | |
|-------|------|----|
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |
| Owner | From | To |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  SK59HDJ |
| Plate since | 2019-09-29 |
| Current registration |  SK59HDJ |
| Plate since | 2019-09-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 21 |
| First mileage registration | 2009-10-31 |
| Last registration | 2024-02-06 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2009-10-31 | 7 mi |
| Registration #2 | 2012-10-22 | 12.582 mi |
| Registration #3 | 2013-09-05 | 17.115 mi |
| Registration #4 | 2014-02-07 | 17.486 mi |
| Registration #5 | 2015-01-22 | 23.702 mi |
| Registration #6 | 2016-01-12 | 30.573 mi |
| Registration #7 | 2016-01-12 | 30.573 mi |
| Registration #8 | 2017-01-31 | 38.435 mi |
| Registration #9 | 2017-01-31 | 38.435 mi |
| Registration #10 | 2018-01-25 | 46.910 mi |
| Registration #11 | 2019-02-01 | 63.369 mi |
| Registration #12 | 2019-02-01 | 63.369 mi |
| Registration #13 | 2019-02-01 | 63.369 mi |
| Registration #14 | 2019-02-01 | 63.369 mi |
| Registration #15 | 2019-02-01 | 63.369 mi |
| Registration #16 | 2019-02-01 | 63.369 mi |
| Registration #17 | 2019-02-01 | 63.369 mi |
| Registration #18 | 2019-02-01 | 63.369 mi |
| Registration #19 | 2019-02-01 | 63.369 mi |
| Registration #20 | 2019-02-01 | 63.369 mi |
| Registration #21 | 2019-02-01 | 63.369 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1950 mm |
| Height | 1543 mm |
| Length | 4013 mm |
| Wheel base | 2485 mm |
| Kerb weight | 1161 kg |
| Max. allowed weight | 1605 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|-----------------|---------|
| Number of axles | 2 |
| Engine number | 9C86848 |