



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 D-4D XT3
Colour	Grey
Year of manufacture	2005
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	250 Nm at 1.800 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	39.8 mpg
CO2 emission	190 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-02-05
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-08-06
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	44
Total items failed	7

MOT #18	2023-07-07 12:40
MOT test number	430753392396
Result	✓ Passed
Next expiry date	2024-08-06
Advice	Gearbox mounting defective
Advice	Front Anti-roll bar linkage ball joint has slight play both (5.3.4 (a) (i))

MOT #17	2022-08-04 09:43
MOT test number	758298717949
Result	✓ Passed
Advice	Front Lower Tyre slightly damaged/cracking or perishing both front tyres cracked and perished (5.2.3 (d) (ii))
Advice	Front Headlamp has a product on the light source but not seriously reducing light output lenses faded (4.1.4 (b))
Advice	Rear Tyre slightly damaged/cracking or perishing both rear tyres cracked and perished (5.2.3 (d) (ii))
Advice	Central Front Lower Oil leak, but not excessive (8.4.1 (a) (i))

MOT #16	2021-07-26 11:13
MOT test number	322329766882
Result	✓ Passed

**MOT #15**

2020-08-07 09:54

MOT test number

867656986991

Result

✓ Passed

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #14**

2019-10-22 13:30

MOT test number

805525079467

Result

✓ Passed

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**MOT #13**

2018-05-25 09:32

MOT test number

729076912223

Result

✓ Passed

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #12**

2018-02-03 16:02

MOT test number

622744831788

Result

✓ Passed

- Advice** Oil leak
- Advice** Rear Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Offside Rear Suspension spring mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Nearside Rear Suspension spring mounting prescribed area is corroded but not considered excessive (2.4.A.3)

MOT #11

2018-01-30 08:52

MOT test number

231839524722

Result

✗ Failed

- Advice** Offside Rear Suspension spring mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Advice** Front Sub-frame corroded but not seriously weakened (2.4.G.1)
- Advice** Nearside Rear Suspension spring mounting prescribed area is corroded but not considered excessive (2.4.A.3)
- Fail** Offside Rear coil spring broken (2.4.C.1a)
- Advice** Oil leak
- Advice** Rear Sub-frame corroded but not seriously weakened (2.4.G.1)

**MOT #10** 2017-05-17 10:32**MOT test number** 760820327654**Result** ✓ Passed

- Advice** Offside Front perishing
- Advice** Brake hose has slight corrosion to ferrules all hoses (3.6.B.4e)
- Advice** Brake components corroded .. brake discs front and rear corroded
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Front and rear suspension components very heavily corroded
- Advice** Corrosion on under side

MOT #9 2015-10-20 11:14**MOT test number** 156018775888**Result** ✓ Passed**MOT #8** 2014-11-18 12:16**MOT test number** 118912724380**Result** ✓ Passed

- Notice** Corrosion on suspension componets
- Notice** Corrosion on under side
- Notice** Front tyre near side worn

**MOT #7** 2014-11-12 14:42**MOT test number** 477516814472**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Corrosion on under side**Notice** Front tyre near side worn**Notice** Corrosion on suspesion componets**MOT #6** 2013-01-31 12:42**MOT test number** 948781933060**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Corrosion to engine oil filter**MOT #5** 2013-01-31 08:09**MOT test number** 408981833073**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Rear An item not tested (Manual)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Corrosion to engine oil filter**Fail** Offside Front Mechanical brake component has restricted free movement (3.5.1k)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Mechanical brake component has restricted free movement (3.5.1k)**Notice** Corrosion to front brake discs

**MOT #4** 2012-01-31 09:30**MOT test number** 377411432013**Result** ✓ Passed**Notice** Nearside front windscreen wiper blade beginning to split but still clearing screen**MOT #3** 2010-12-21 12:34**MOT test number** 423045350482**Result** ✓ Passed**MOT #2** 2009-11-27 15:01**MOT test number** 404661139370**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2008-12-05 12:59**MOT test number** 271960948372**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
12 October 2023

✓

MOT

Expires:
6 August 2024

Tax status	Expired at 12 October 2023
Days left	200 days too late
MOT expiry date	6 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	GR55XKM
Plate since	2019-03-29
Current registration	GR55XKM
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-12-22
Last registration	2023-07-07
Complete history	See info



Registration #1	2005-12-22	18 mi
Registration #2	2008-12-05	19.510 mi
Registration #3	2009-11-27	26.911 mi
Registration #4	2010-12-21	34.405 mi
Registration #5	2012-01-31	44.432 mi
Registration #6	2013-01-31	48.546 mi
Registration #7	2013-01-31	48.546 mi
Registration #8	2014-11-12	52.047 mi
Registration #9	2014-11-18	52.051 mi
Registration #10	2015-10-20	53.936 mi
Registration #11	2015-10-20	53.936 mi
Registration #12	2015-10-20	53.936 mi
Registration #13	2015-10-20	53.936 mi
Registration #14	2015-10-20	53.936 mi
Registration #15	2015-10-20	53.936 mi
Registration #16	2015-10-20	53.936 mi
Registration #17	2015-10-20	53.936 mi
Registration #18	2015-10-20	53.936 mi
Registration #19	2015-10-20	53.936 mi
Registration #20	2015-10-20	53.936 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video

[see crash video](#)



Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1490 kg
Max. allowed weight	1930 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1CD0491619