




report date: 2024-03-29

General information

Make	VAUXHALL
Model	MOVANO F3500 L3H1 C/C CDTi
Colour	White
Year of manufacture	2016
Top speed	80 mph
0 - 60 mph	14.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	310 Nm at 2.500 rpm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	35.0 mpg
Consumption combined	32.0 mpg
CO2 emission	226 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-08-21
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-15
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	18
Total items failed	10

MOT #7	2024-02-16 15:21
MOT test number	821522263432
Result	✓ Passed
Next expiry date	2025-02-15
Minor	Nearside Direction indicator lens defective which has no effect on emitted light lens in mirror damaged (4.4.1 (b) (i))

MOT #6	2024-02-14 09:28
MOT test number	315664370740
Result	✗ Failed
Fail	Nearside Rear Position lamp not working (4.2.1 (a) (ii))
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Minor	Nearside Rear Stop lamp(s) lens defective which has no effect on emitted light lens damaged (4.3.1 (b) (i))
Fail	Service brake efficiency below requirements (1.2.2 (a) (i))
Fail	Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Minor	Nearside Direction indicator lens defective which has no effect on emitted light lens in mirror damaged (4.4.1 (b) (i))
Fail	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Fail	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #5** 2023-01-12 16:24**MOT test number** 646396585484**Result** ✓ Passed**MOT #4** 2021-10-25 13:58**MOT test number** 158542065970**Result** ✓ Passed**MOT #3** 2020-06-02 15:19**MOT test number** 970320719475**Result** ✓ Passed**MOT #2** 2019-05-08 14:50**MOT test number** 452358350258**Result** ✓ Passed**Advice** Rear suspension sitting down on spring assisters**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Upper/lower engine covers fitted**Advice** Items removed from driver's view prior to test**Advice** Wiper blades worn but meet requirements**Advice** Vehicles internal headlight adjuster altered to recheck lights**Minor** Offside Rear Outline marker lamp insecure (4.2.1 (c) (i))



MOT #1	2019-05-07 08:12
MOT test number	146510564402
Result	✗ Failed
Fail	Nearside Body component damaged and likely to cause injury door mirror (6.2.1 (a) (i))
Advice	Wiper blades worn but meet requirements
Minor	Offside Direction indicator flashing more than 120 times a minute (4.4.4 (a))
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))
Advice	Rear suspension sitting down on spring assisters
Advice	Items removed from driver's view prior to test
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))
Advice	Upper/lower engine covers fitted
Advice	Vehicles internal headlight adjuster altered to recheck lights
Minor	Offside Rear Outline marker lamp insecure (4.2.1 (c) (i))
Fail	Offside Direction indicator not working siderepeater (4.4.1 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
15 February 2025

Tax status	Valid until 1 October
Days left	154
MOT expiry date	15 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 FL16YJY
Plate since	2019-03-29
Current registration	 FL16YJY
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-05-10
Last registration	2024-02-16
Complete history	See info



Registration #1	2016-05-10	15 mi
Registration #2	2019-05-07	30.123 mi
Registration #3	2019-05-08	30.123 mi
Registration #4	2020-06-02	60.421 mi
Registration #5	2020-06-02	60.421 mi
Registration #6	2020-06-02	60.421 mi
Registration #7	2020-06-02	60.421 mi
Registration #8	2020-06-02	60.421 mi
Registration #9	2020-06-02	60.421 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2470 mm
Height	2350 mm
Length	6418 mm
Kerb weight	1686 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Engine number	M9T -C199830 LWL