





report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI GO
Colour	White
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	50.4 mpg
CO2 emission	147 g/km
CO2 label	F



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-05-10
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	15
Total items failed	3

MOT #10	2024-04-22 12:09
MOT test number	714323523774
Result	✓ Passed
Next expiry date	2025-05-10
Advice Child Seat fitted not allowing full inspection of adult belt	
Advice Items removed from driver's view prior to test	
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #9	2024-04-22 12:09
MOT test number	211388821804
Result	× Failed
Advice Child Seat fitted not allowing full inspection of adult belt	
Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice Items removed from driver's view prior to test	
Pass with rectification Offside Headlamp aim too high (4.1.2 (a))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8 2023-05-11 09:41

MOT test number 535554220133

Result ✓ Passed

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 2.87mm (5.2.3 (e))

Minor Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #7 2022-04-05 10:49

MOT test number 189762828456

Result \square Passed

Advice Offside rear tyre deteriorated slightly

MOT #6 2022-03-23 11:16

MOT test number 693689527999

Result X Failed

Advice Offside rear tyre deteriorated slightly

Fail Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt also play in ball joint (2.1.3 (g) (ii))

MOT #5 2021-04-08 10:28

MOT test number 165390048044

Result
✓ Passed

MOT #4 2021-03-30 11:53

MOT test number 918171153662

Result X Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/12



MOT #3	2019-04-08 12:07
MOT test number	587573378054
Result	✓ Passed
MOT #2	2018-04-03 07:54
MOT test number	510492984796
Result	✓ Passed

MOT #1		2017-03-31 08:44
MOT test	number	855138521909
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	10 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info

CarCheck.co.uk page 9/12



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-03-31
Last registration	2024-04-22
Complete history	See info



Registration #1	2014-03-31	19 mi
Registration #2	2017-03-31	23.423 mi
Registration #3	2018-04-03	34.639 mi
Registration #4	2019-04-08	46.060 mi
Registration #5		11.777 es
Registration #6	2021-03-30	60.409 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		
Registration #9		
Registration #10		0.074
		11.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12

Engine number

D4FDEZ280515