






report date: 2024-03-28

General information

Make	MINI
Model	MINI COOPER S
Colour	Green
Year of manufacture	2013
Top speed	141 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	190 BHP
Max. torque	260 Nm at 1.700 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	Е



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-23

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT I	nistory
-------	---------

MOT expiry date	2024-05-12
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	17
Total items failed	5

MOT #13	2023-05-12 09:21
MOT test number	157602967076
Result	✓ Passed
Next expiry date	2024-05-12

MOT #12	2022-05-13 15:20
MOT test number	322824872833
Result	✓ Passed

MOT #11	2022-05-13 11:17
---------	------------------

MOT test number 971839188280

Result X Failed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #10	2022-04-04 11:42
MOT test number	249917718332
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2021-05-04 14:23

MOT test number 754723705651

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1

(b) (i))

MOT #8 2021-05-01 09:17

MOT test number 413519184398

Result X Failed

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Windscreen washer not working (3.5 (a))

MOT #7 2019-12-12 09:49

MOT test number 332520775125

Result

Passed

Advice O/S plate light n/w

Advice TPMS light at dash stays ON

Advice Small cracks at screen

MOT #6 2019-01-03 10:44

MOT test number 507675922018

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT test number

Result

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice

Brake warning lamp at dashboard illuminated.

Advice

Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #4	2017-02-16 15:37
MOT test i	umber 503353170533
Result	✓ Passed
Advice	Rear inner b/pads appear abit low
Advice wear)	Front inner b/pads appear abit low, and outer pads getting low (esp O/S outer pad, nearing limit of
Advice	Small cracks at screen

MOT #3		2016-02-22 15:40
MOT test number		904709065345
Result		✓ Passed
MOT #2		2015-02-25 14:42
MOT test number		419376555045
Result		✓ Passed
MOT #1		2015-02-25 14:42
MOT test number		977446055036
Result		X Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	12 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12




report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

YF62AKP

report date: 2024-03-28

	For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have Check it in the premium report and see all owner registrations. Download the full report here .	/e?
1		
1		
1		

More info >

Plate changes

More info >

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-01-14
Last registration	2023-05-12
Complete history	See info



Registration #1	2013-01-14	14 mi
Registration #2	2015-02-25	22.813 mi
Registration #3	2016-02-22	31.034 mi
Registration #4	2017-02-16	42.265 mi
Registration #5	2018-01-25	49.054 mi
Registration #6	2019-01-03	52.938 mi
Registration #7	2019-12-12	60.239 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		
Registration #11		0.00 44
Registration #12		1.77 4
		1.77 m

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1892 mm
Height	1390 mm
Length	3734 mm
Wheel base	2467 mm
Kerb weight	1185 kg
Max. allowed weight	1475 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats CarCheck.co.uk	2 page 12/