



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	CC GT TDI BLUEMOTION TECHNOLOGY
Colour	Grey
Year of manufacture	2012
Top speed	133 mph
0 - 100 km/h	9.8 seconds
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	120 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-07-11
Pictures	9
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-05-12
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	24
Total items failed	8

MOT #11 2022-05-13 11:29

MOT test number 904268958191

Result ✓ Passed

Next expiry date 2023-05-12

- Advice** Nsr tyre uneven wear inner edge, outer sidewall damage
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush worn (5.3.4 (a) (i))
- Advice** Damage windscreen zone a
- Advice** Osr tyre uneven wear inner edge
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush worn (5.3.4 (a) (i))

MOT #10 2021-02-17 12:09

MOT test number 172319402081

Result ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2mm in centre (5.2.3 (e))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush worn (5.3.4 (a) (i))
- Advice** Rear Inner Tyre slightly damaged/cracking or perishing both rear misshapen on inners (5.2.3 (d) (ii))

**MOT #9**

2021-02-16 12:17

MOT test number

288782272028

Result**✗ Failed**

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush worn (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 2mm in centre (5.2.3 (e))

Fail Front Headlamp aim too low both fronts (4.1.2 (a))

Advice Rear Inner Tyre slightly damaged/cracking or perishing both rear misshapen on inners (5.2.3 (d) (ii))

Fail Front Headlamp levelling device inoperative both front sensors have broken (4.1.5 (a))

MOT #8

2020-02-17 16:16

MOT test number

323061414312

Result**✓ Passed**

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement rear bushes both sides deteriorated slightly (5.3.4 (a) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened inner faces corroded recommend changing next time pads are done (1.1.14 (a) (ii))

Advice Offside Front Brake pad(s) wearing thin check again in 2000 miles (1.1.13 (a) (ii))

MOT #7

2019-01-30 17:12

MOT test number

306922722054

Result**✓ Passed****MOT #6**

2019-01-30 11:10

MOT test number

200142950214

Result**✗ Failed**

Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #5** 2018-02-21 10:47**MOT test number** 568453291197**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit 3mm and 1mm on inner edge. (4.1.E.1)**Advice** Nearside Rear tyre has a cut in outer side wall but not showing ply or cords.**Advice** Nearside Rear Tyre worn close to the legal limit 3mm and 1mm on inner edge. (4.1.E.1)**MOT #4** 2018-02-21 10:47**MOT test number** 744164644213**Result** ✗ Failed**Pass with rectification** Rear registration plate character(s) incorrectly spaced (6.3.4a)**Advice** Offside Rear Tyre worn close to the legal limit 3mm and 1mm on inner edge. (4.1.E.1)**Pass with rectification** Front registration plate character(s) incorrectly spaced (6.3.4a)**Advice** Nearside Rear Tyre worn close to the legal limit 3mm and 1mm on inner edge. (4.1.E.1)**Advice** Nearside Rear tyre has a cut in outer side wall but not showing ply or cords.**MOT #3** 2017-02-14 16:36**MOT test number** 490725142411**Result** ✓ Passed**MOT #2** 2015-12-02 15:30**MOT test number** 554984828025**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2015-12-02 12:30
MOT test number	803741915446
Result	✗ Failed
Fail	Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
Advice	Nearside Front Inner Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
Advice	Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

X

Untaxed

Tax expired:
1 August 2022

X

MOT

Expired:
12 May 2023

Tax status	Expired at 1 August 2022
Days left	637 days too late
MOT expiry date	12 May 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	WG62FXJ
Plate since	2019-06-29
Current registration	WG62FXJ
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-12-07
Last registration	2022-05-13
Complete history	See info



Registration #1	2012-12-07	19 mi
Registration #2	2015-12-02	35.020 mi
Registration #3	2015-12-02	35.020 mi
Registration #4	2017-02-14	47.552 mi
Registration #5	2018-02-21	67.114 mi
Registration #6	2018-02-21	67.114 mi
Registration #7	2019-01-30	79.332 mi
Registration #8	2019-05-29	91.557 mi
Registration #9	2019-05-29	91.557 mi
Registration #10	2019-05-29	91.557 mi
Registration #11	2019-05-29	91.557 mi
Registration #12	2019-05-29	91.557 mi
Registration #13	2019-05-29	91.557 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	77%
Pedestrian	54%
Safety systems	71%
Overall rating	79%
Video	see crash video



Dimensions & weight

Width	2090 mm
Height	1421 mm
Length	4902 mm
Wheel base	2710 mm
Kerb weight	1550 kg
Max. allowed weight	2050 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	CFFBD24555