





report date: 2024-03-29

General information

Make	CITROEN
Model	C4 GRAND BLUEHDI FLAIR S/S
Colour	Blue
Year of manufacture	2016
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	74.3 mpg
Consumption combined	70.6 mpg
CO2 emission	106 g/km
CO2 label	В



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

-		-		1
п	L	ΓV	,	т.

Entry 1	
Date	2022-05-26
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-03-12
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	32
Total items failed	3

MOT #8	2024-03-08 12:52
MOT test number	664700724954
Result	✓ Passed
Next expiry date	2025-03-12

MOT #	7	2024-03-05 15:07
MOT te	st number	731450073505
Result		X Failed
Fail (ii))	Rear Inner Brake disc in such a condition that it is seriously weakened I	BOTH INNER SIDE (1.1.14 (a)

MOT #6	2023-03-07 12:19
MOT test number	819036391705
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #5 2022-03-05 12:01 525127835958 **MOT** test number ✓ Passed Result **Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4	20	022-03-04 16:49
MOT test	number	435607990458
Result		X Failed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail C	offside Front Tyre has a lump, caused by separation or partial failure of its structure (5	.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail	earside Front Tyre has a lump, caused by separation or partial failure of its structure	(5.2.3 (d) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #3		2021-03-04 11:36
MOT test	number	881400208665
Result		✓ Passed
Advice	Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing with slight lump to tre	ead (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Rear Inner Brake disc worn, pitted or scored, but not seriously weakened	d (1.1.14 (a) (ii))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #2		2020-03-06 14:14
MOT test	number	982264305827
Result		✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1	1.14 (a) (ii))
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1	14 (a) (ii))
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 5/13



MF66VLC report date: 2024-03-29

MOT #1 2019-03-13 14:16

MOT test number 392316735641

Result ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	34
MOT expiry date	12 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
Annual Control of the	

THE STREET STREET	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	NK SIX
Plate since	
Current registration	NK NY
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



MF66VLC report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-09-12
Last registration	2024-03-08
Complete history	See info



Registration #1	2016-09-12	12 mi
Registration #2	2019-03-13	11.170 mi
Registration #3	2020-03-06	20.366 mi
Registration #4	2021-03-04	25.425 mi
Registration #5	2022-03-04	34.409 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #7 Registration #8		11.777 es
		11,777 es

More info >

CarCheck.co.uk page 12/13



MF66VLC report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	90%
Children	85%
Pedestrian	43%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1826 mm
Height	1644 mm
Length	4597 mm
Wheel base	2840 mm
Kerb weight	1347 kg
Max. allowed weight	2175 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	JBHR3020094

CarCheck.co.uk page 13/13