





### General information

Make	PEUGEOT
Model	307 S
Colour	Blue
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	12.5 seconds
Gearbox	4 speed automatic


### Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.2 mpg
Consumption extra urban	47.1 mpg
Consumption combined	35.8 mpg



## Internet history

Entry 2	
Date	2023-02-05
Pictures	20
Listing price	View report



source: autotrader.co.uk

Entry 1	
Date	2021-02-03
Pictures	10
Listing price	<u>View report</u>



source: autoonline.co.uk









## MOT history

MOT #17		2023-02-04 15:34
MOT test	number	728384484594
Result		✓ Passed
Next expi	ry date	2024-02-03
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (i	i))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (	ii))

MOT #16	2023-02-03 17:31
MOT test number	601553876207
Result	🗙 Failed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.1	4 (a) (ii))
Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14)	4 (a) (ii))
Fail Front Windscreen washer not working (3.5 (a))	

MOT #15	2022-02-02 11:06
MOT test number	172446329747
Result	✓ Passed
Advice Nearside Front Play in steering rack inner joint(s)	

MOT #14	2021-01-21 13:50
MOT test number	917035271829
Result	✓ Passed





MOT #13	2020-07-15 11:44
MOT test number	701365083458
Result	🗙 Failed
<b>Fail</b> Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))	
Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Steering linkage ball joint has slight play (2.1.3 (b) (i))	
Fail Offside Rear Service brake excessively binding (1.2.1 (f))	
<b>Fail</b> Nearside Front Steering linkage ball joint has excessive play (2.1.3 (b) (i))	
Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail Nearside Rear Service brake excessively binding (1.2.1 (f))	

MOT #12	2019-07-15 09:23
MOT test number	796660767987
Result	✓ Passed
Advice Offside Front Inner Brake pad(s) wearing thin inner pad (1.1.13 (a) (ii))	

MOT #11	2018-07-18 12:45
MOT test number	559608977648
Result	✓ Passed

MOT #10	2018-07-16 12:08
MOT test number	798743793551
Result	🗙 Failed
FailNearside Front Upper Anti-roll bar ball joint dust cover no longer preven(ii))	ts the ingress of dirt (5.3.4 (b)





MOT #9		2017-06-13 10:44
MOT test	number	938386133693
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Play in steering rack inner joint(s)	
Advice	Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)	

MOT #8	2016-06-16 12:16
MOT test number	950513329038
Result	✓ Passed
Advice Nearside Play in steering rack inner joint(s)	

MOT #7	2015-06-02 10:18
MOT test number	118053155171
Result	✓ Passed

МОТ #6	2014-06-05 15:46
MOT test number	277796254463
Result	✓ Passed
<b>Notice</b> Play in steering rack inner joint(s)	

MOT #5	2013-06-12 17:06
MOT test number	387703563110
Result	✓ Passed
MOT #4	2012 05 28 12:40

MOT #4	2012-05-28 12:49
MOT test number	276099142419
Result	✓ Passed





MOT #3	2011-05-31 10:53
MOT test number	388441251169
Result	✓ Passed
MOT #2	2010-06-22 09:03
MOT test number	140663470182
Result	✓ Passed
MOT #1	2009-10-22 12:13
MOT test number	250435799242
Result	✓ Passed





#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Date	
Category	AMPL
Туре	

#### Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
********	
*******	
***********	
********	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





## Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-10-27
Last registration	2023-02-04
Complete history	See info



Registration #1	2006-10-27	26 mi
Registration #2	2009-10-22	24.003 mi
Registration #3	2010-06-22	27.201 mi
Registration #4	2011-05-31	33.362 mi
Registration #5	2012-05-28	37.320 mi
Registration #6	2013-06-12	41.200 mi
Registration #7	2014-06-05	43.552 mi
Registration #8	2015-06-02	47.012 mi
Registration #9	2016-06-16	48.504 mi
Registration #10	2017-06-13	53.761 mi
Registration #11		11.117 esi
Registration #12		11.117 est
Registration #13		11.117 esi
Registration #14		11.777 est
Registration #15		11.117 esi
Registration #16		11.117 est
Registration #17		11.117 esi
Registration #18		11.177 est
Registration #19		11.777 mi
Registration #20		11.777 est

More info >





#### Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
\$0566	
\$0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1757 mm
Height	1530 mm
Length	4211 mm
Wheel base	2608 mm
Kerb weight	1318 kg
Max. allowed weight	1725 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	FX6Q2946232