



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA VVT LIFE
Colour	Silver
Year of manufacture	2008
Top speed	123 mph
0 - 60 mph	11.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	47.9 mpg
Consumption combined	37.7 mpg
CO2 emission	180 g/km
CO2 label	I






Internet history

Entry 2


Date	2021-08-12
Pictures	13
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-08-11
Pictures	13
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-18
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	9
Total items failed	9

MOT #17	2024-02-19 15:33
MOT test number	895990934312
Result	✓ Passed
Next expiry date	2025-02-18

MOT #16	2022-10-07 08:38
MOT test number	610400046144
Result	✓ Passed

MOT #15	2021-09-02 17:04
MOT test number	480966620247
Result	✓ Passed

MOT #14	2021-09-02 17:04
MOT test number	261279228135
Result	✗ Failed
Pass with rectification	Nearside Headlamp incorrect colour (4.1.4 (a))
Pass with rectification	Offside Headlamp incorrect colour (4.1.4 (a))

**MOT #13** 2021-08-17 16:01**MOT test number** 455805697054**Result** ✗ Failed

- Fail** Offside Front Headlamp incorrect colour red (4.1.4 (a))
- Fail** Nearside Front Headlamp incorrect colour red (4.1.4 (a))
- Fail** Oil leaking excessively from engine (8.4.1 (a) (i))

MOT #12 2020-10-20 10:42**MOT test number** 485380807672**Result** ✓ Passed

- Advice** Under bonnet covers fitted restricting inspection
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11 2020-10-20 10:42**MOT test number** 238386390033**Result** ✗ Failed

- Pass with rectification** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Pass with rectification** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Under bonnet covers fitted restricting inspection
- Pass with rectification** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #10 2019-03-29 14:47**MOT test number** 671476104169**Result** ✓ Passed

**MOT #9** 2019-03-29 09:55**MOT test number** 605213169940**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2018-03-28 14:46**MOT test number** 187198228510**Result** ✓ Passed**MOT #7** 2017-03-29 12:20**MOT test number** 338133468830**Result** ✓ Passed**MOT #6** 2016-03-29 11:10**MOT test number** 200002516871**Result** ✓ Passed**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**Advice** Offside Rear coil spring corroded (2.4.C.1b)**MOT #5** 2015-04-13 16:44**MOT test number** 679373605169**Result** ✓ Passed**MOT #4** 2014-04-14 17:09**MOT test number** 479724704152**Result** ✓ Passed

**MOT #3** 2013-11-15 13:36**MOT test number** 835879313320**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-11-07 12:16**MOT test number** 447072512343**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2011-10-29 10:43**MOT test number** 455692101450**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
31 January 2024

✓

MOT

Expires:
18 February 2025

Tax status	Expired at 31 January 2024
Days left	89 days too late
MOT expiry date	18 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 MJ58BNZ
Plate since	2019-06-29
Current registration	 MJ58BNZ
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-11-25
Last registration	2024-02-19
Complete history	See info



Registration #1	2008-11-25	27 mi
Registration #2	2011-10-29	14.560 mi
Registration #3	2012-11-07	27.347 mi
Registration #4	2013-11-15	37.366 mi
Registration #5	2014-04-14	39.588 mi
Registration #6	2015-04-13	43.212 mi
Registration #7	2016-03-29	46.374 mi
Registration #8	2017-03-29	48.702 mi
Registration #9	2018-03-28	50.322 mi
Registration #10	2019-03-29	52.591 mi
Registration #11	2020-03-29	52.591 mi
Registration #12	2021-03-29	52.591 mi
Registration #13	2022-03-29	52.591 mi
Registration #14	2023-03-29	52.591 mi
Registration #15	2024-03-29	52.591 mi
Registration #16	2025-03-29	52.591 mi
Registration #17	2026-03-29	52.591 mi
Registration #18	2027-03-29	52.591 mi
Registration #19	2028-03-29	52.591 mi
Registration #20	2029-03-29	52.591 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4824 mm
Wheel base	2830 mm
Kerb weight	1400 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20LS0295