





report date: 2024-03-28

General information

Make	VOLKSWAGEN	
Model	GOLF GTI PERFORMANCE TSI	
Colour	Blue	
Year of manufacture	2018	
Top speed	155 mph	
0 - 100 km/h	6.4 seconds	
0 - 60 mph	6.0 seconds	
Gearbox	6 speed Manual	

Engine & fuel consumption

Power	169 kW / 230 HP / 242 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg
CO2 emission	148 g/km
CO2 label	F



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-10-16

Pictures 33

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-11-04
MOT pass rate	100 %
MOT passed	4
Failed MOT tests	0
Total advice items	12
Total items failed	0

MOT #4		2023-11-01 11:00
MOT test	number	228855604444
Result		✓ Passed
Next expi	ry date	2024-11-04
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened	l Lipped (1.1.14 (a) (ii))
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakene	ed Corroded (1.1.14 (a)
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened	ed Lipped (1.1.14 (a)
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice (ii))	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	Corroded (1.1.14 (a)

MOT #3	2022-10-27 09:35
MOT test number	156925492029
Result	✓ Passed

MOT #2	2021-11-05 09:09
MOT test number	190888578848
Result	✓ Passed

CarCheck.co.uk page 3/11



Advice

VX68WJD
report date: 2024-03-28

MOT #1 2021-09-13 10:10

MOT test number

Result

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge worn smooth inner (5.2.3 (e))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge worn smooth inner (5.2.3 (e))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Offside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 May
Days left	368
MOT expiry date	4 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Type

Date

Damage 2

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

2000000	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	OK SILE
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-09-14
Last registration	2023-11-01
Complete history	See info



Registration #1	2018-09-14	24 mi
Registration #2	2021-09-13	30.892 mi
Registration #3		11.777 es
Registration #4		71.777 66
Registration #5		11,177 es
Pogistration #6		

Registration #6

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	89%
Pedestrian	65%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2027 mm
Height	1482 mm
Length	4268 mm
Wheel base	2626 mm
Kerb weight	1286 kg

Additional information

Fuel tank capacity 50 l	
Tuel talk capacity	
Fuel delivery Direct Injection	
Number of doors 3	
Number of axles 2	

CarCheck.co.uk page 11/11

Engine number

DLBA016403