





General information

Make	PEUGEOT
Model	207 S
Colour	Grey
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	15.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	118 Nm at 3.300 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.6 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.8 mpg





YW60

Internet history


Entry 1	
Date	202
Pictures	14

21-06-09

14

Listing price

View report



source: autotrader.co.uk



MOT history

МОТ #15	2023-03-23 11:18
MOT test number	713828122651
Result	✓ Passed
Next expiry date	2024-03-22
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps of (4.7.1 (b) (i))	or light sources

MOT #14		2023-03-23 11:18
MOT test number		986218164234
Result		🗙 Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid	(3.5 (a))
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Front Oil leak, but not excessive (8.4.1 (a) (i))		
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		

MOT #13	2022-02-21 13:55
MOT test number	709401356126
Result	✓ Passed
 Advice Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) 	





MOT #12	2022-02-21 13:	55
MOT test number	6433272414	39
Result	× Faile	ed
Pass with rectificat	n Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Front Brake	disc worn, but not excessively both sides (1.1.14 (a) (i))	

MOT #11		2021-02-15 13:23
MOT test	number	973944651710
Result		✓ Passed
Advice	Offside Front Nail in tyre	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10		2020-02-12 13:26
MOT test numb	er	210424672965
Result		✓ Passed
Advice Rear	Exhaust mounting defective Broken (6.1.2 (a))	
Advice Oil le	eak, but not excessive (8.4.1 (a) (i))	

МОТ #9	2020-02-12 13:26	
MOT test number	694954245372	
Result	× Failed	
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))	
Advice Oil leak, but not	excessive (8.4.1 (a) (i))	
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))	
Pass with rectification	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Advice Rear Exhaust mounting defective Broken (6.1.2 (a))		





MOT #8		2019-02-07 15:03
MOT test	number	925002109459
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
MOT #7		2018-02-14 09:07
MOT #7 MOT test	number	2018-02-14 09:07 954029499788
	number	

MOT #6		2018-02-14 09:07
MOT test number		732855367954
Result		🗙 Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)	
Advice Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)		
Pass with rectification	Offside Registration plate lamp not working (1.1.C.1d)	

MOT #5	2017-02-15 09:00
MOT test number	487159003272
Result	✓ Passed
MOT #4	2016-02-11 12:49
MOT test number	610107637412
Result	✓ Passed



report date: 2024-03-29

MOT #3		2015-02-17 11:08
MOT test r	number	436908245018
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)	
MOT #2		2014-02-21 16:04

MOT test number	756112354073
Result	✓ Passed
MOT #1	2014-02-20 16:36

MOT te	est number	125861354443
Result		🗙 Failed
Fail	Offside Front coil spring broken (2.4.C.1a)	
Fail	Headlamp aim too low (1.8)	





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEM PE
Туре	
Damage 2	Annet
Date	No. Contraction of the second
Category	AMP
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-09-24
Last registration	2023-03-23
Complete history	See info



Registration #1 2010/03/24 12 mi Registration #2 2014/02/20 23.731 mi Registration #3 2014/02/21 23.731 mi Registration #3 2014/02/21 23.731 mi Registration #4 2015/02/17 25.978 mi Registration #5 2016/02/11 27.152 mi Registration #6 2017/02/15 32.471 mi Registration #7 2018/02/14 49.964 mi Registration #7 2019/02/07 62.753 mi Registration #10 Italian Italian Registration #11 Italian Italian Registration #12 Italian Italian Registration #13 Italian Italian Registration #14 Italian Italian Registration #15 Italian Italian Registration #16 Italian Italian Registration #17 Italian Italian	Registration #1	2010-09-24	12 mi
Registration #3 2014-02-21 23.731 mi Registration #4 2015-02-17 25.978 mi Registration #5 2016-02-11 27.152 mi Registration #6 2017-02-15 32.471 mi Registration #6 2018-02-14 49.964 mi Registration #8 2018-02-14 49.964 mi Registration #9 2019-02-07 62.753 mi Registration #10 Image: Stration #10 Image: Stration #10 Registration #11 Image: Stration #10 Image: Stration #11 Registration #12 Image: Stration #12 Image: Stration #12 Registration #13 Image: Stration #14 Image: Stration #15 Registration #15 Image: Stration #16 Image: Stration #16		2010-09-24	12 1111
Registration #4 2015-02-17 25.978 mi Registration #5 2016-02-11 27.152 mi Registration #6 2017-02-15 32.471 mi Registration #7 2018-02-14 49.964 mi Registration #8 2018-02-14 49.964 mi Registration #9 2019-02-07 62.753 mi Registration #10 Image: Stration #10 Image: Stration #10 Registration #11 Image: Stration #11 Image: Stration #11 Registration #12 Image: Stration #12 Image: Stration #14 Registration #14 Image: Stration #15 Image: Stration #16	Registration #2	2014-02-20	23.731 mi
Registration #5 2016-02-11 27.152 mi Registration #6 2017-02-15 32.471 mi Registration #7 2018-02-14 49.964 mi Registration #8 2018-02-14 49.964 mi Registration #8 2019-02-07 62.753 mi Registration #10 1 1 Registration #11 1 1 Registration #12 1 1 Registration #13 1 1 Registration #14 1 1 Registration #15 1 1	Registration #3	2014-02-21	23.731 mi
Registration #6 2017-02-15 32.471 mi Registration #7 2018-02-14 49.964 mi Registration #8 2018-02-14 49.964 mi Registration #8 2019-02-07 62.753 mi Registration #10 Image: Comparison of the second	Registration #4	2015-02-17	25.978 mi
Registration #7 2018-02-14 49.964 mi Registration #8 2018-02-14 49.964 mi Registration #9 2019-02-07 62.753 mi Registration #10 Image: Comparison of the second secon	Registration #5	2016-02-11	27.152 mi
Registration #82018-02-1449.964 miRegistration #92019-02-0762.753 miRegistration #10IIRegistration #11IIRegistration #12IRegistration #13IIRegistration #14IIRegistration #15IRegistration #16I	Registration #6	2017-02-15	32.471 mi
Registration #92019-02-0762.753 miRegistration #1062.753 miRegistration #1162.753 miRegistration #1162.753 miRegistration #1262.753 miRegistration #1362.753 miRegistration #1462.753 miRegistration #1562.753 miRegistration #1662.753 mi	Registration #7	2018-02-14	49.964 mi
Registration #10Registration #11Registration #12Registration #13Registration #14Registration #15Registration #16	Registration #8	2018-02-14	49.964 mi
Registration #11Registration #12Registration #13Registration #14Registration #15Registration #16	Registration #9	2019-02-07	62.753 mi
Registration #12 Registration #13 Registration #14 Registration #15 Registration #16	Registration #10		11.777 esi
Registration #13 Registration #14 Registration #15 Registration #16	Registration #11		11.777 esi
Registration #14 Registration #15 Registration #16	Registration #12		11.777 esi
Registration #15 Registration #16	Registration #13		11.777 esi
Registration #16	Registration #14		
			11.117 ma
Registration #17	-		11.777 es
	Registration #15		11.777 es





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1972 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1215 kg
Max. allowed weight	1617 kg
Additional information	
Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

page 12/12

Number of axles	2
Engine number	FSW86309213