





report date: 2024-03-29

General information

Make	NISSAN
Model	FIGARO
Colour	Blue
Year of manufacture	1991
Gearbox	-

Engine & fuel consumption

Engine capacity	987 cc
Fuel type	Petrol



CarCheck.co.uk page 1/18



Internet history

Entry 1

Date 2021-11-09

Pictures 21

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/18



MOT history

MOT expiry date	2024-09-11
MOT pass rate	65 %
MOT passed	15
Failed MOT tests	8
Total advice items	62
Total items failed	31

MOT #23		2023-09-12 13:51
MOT test n	umber	505164248256
Result		✓ Passed
Next expir	y date	2024-09-11
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material	corroded (1.1.11 (c))
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteri	iorated (5.3.4 (b) (i))
Advice	All four tyres perishing within tread pattern	
Advice	Nearside Front Coil spring corroded (5.3.1 (b) (i))	

CarCheck.co.uk page 3/18



MOT #22 2023-09-07 14:48

MOT test number 746477146345

Result × Failed Fail Service brake efficiency less than 50% of the required value (1.2.2 (a) (ii)) Fail Offside Parking brake inoperative on one side (1.4.1 (a)) **Advice** Oil leak, but not excessive (8.4.1 (a) (i)) Advice Offside Rear Brake pipe corroded, covered in grease or other material corroded (1.1.11 (c)) Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii)) Fail Brake lever has insufficient reserve travel (1.1.2 (a)) Offside Headlamp aim too low (4.1.2 (a)) Fail Fail Rear fog lamp light intensity significantly reduced (4.5.4 (a)) Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i)) Advice Nearside Front Coil spring corroded (5.3.1 (b) (i)) Advice All four tyres perishing within tread pattern

CarCheck.co.uk page 4/18



report date: 2024-03-29

MOT #21	2023-07-29 09:19
MOT test number	632018529370
Result	X Failed
Fail Offside Rear Parking brake inoperative on one side (1.4.1 (a))	
Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Fail Front Brakes imbalanced across an axle by more than 50% (1.2.1 (b) (ii))	
Fail Brake lever has insufficient reserve travel (1.1.2 (a))	
Fail Service brake efficiency less than 50% of the required value (1.2.2 (a) (ii))	
Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11	(c))

MOT #20	2022-07-06 11:47
MOT test number	148187526721
Result	✓ Passed
MOT #19	2020-09-03 11:21
MOT test number	506040883178
Result	✓ Passed

MOT #18	2020-09-02 14:17
MOT test number	128892831763

Result × Failed

Fail Offside Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced floor (6.1.1 (c) (i))

CarCheck.co.uk page 5/18



report date: 2024-03-29

MOT #17 2019-04-10 14:11

MOT test number 317142003779

Result
✓ Passed

MOT #16 2019-04-03 14:54

MOT test number 449336510971

Result × Failed

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Nearside Front Suspension arm pin or bush excessively worn front (5.3.4 (a) (i))

MOT #15 2018-01-19 14:47

MOT test number 488710043425

Result \rightarrow Passed

Advice Nearside Front Suspension arm has slight play in a pin/bush (2.4.G.2)

MOT #14 2017-01-31 17:58

MOT test number 560036808828

Result
✓ Passed

Advice Both rear tyres on 3mm

Advice Oil leak

CarCheck.co.uk page 6/18



report date: 2024-03-29

MOT #13 2017-01-25 11:09

MOT test number 399025987682

Result

× Failed

Fail Offside Rear Outer Suspension component mounting prescribed area is excessively corroded sill (2.4.A.3)

Fail Offside Rear fog lamp does not emit a steady red light (1.3.2e)

Advice Brake fluid level very low

Advice Wipers not tested

Fail Nearside Headlamp aim too high (1.8)

Advice Both rear tyres on 3mm

Fail Offside Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Nearside Rear Outer Suspension component mounting prescribed area is excessively corroded sill (2.4.A.3)

Fail Parking brake lever has no reserve travel (3.1.6b)

Fail Nearside Rear Brake pipe excessively corroded (3.6.B.2c)

Advice Wipers not tested

Fail Offside Registration plate lamp not illuminating the registration plate (1.1.C.1e)

Advice Oil leak

Fail Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Power steering component(s) leaking rack (2.3.3b)

CarCheck.co.uk page 7/18



MOT #12 2016-01-08 14:00

MOT test number 715708406879

Result ✓ Passed

Advice Nearside Steering rack gaiter deteriorated (2.2.D.2d)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

Advice Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement

(2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

Advice Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt

(2.4.G.2)

MOT #11 2014-12-23 09:32

MOT test number 819987954392

Advice Offside Steering rack gaiter deteriorated (2.2.D.2d)

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

Notice Steering rack is damp with power steering fluid but has no visible leak.

Advice Nearside Steering rack gaiter deteriorated (2.2.D.2d)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Shock absorber has a light misting of oil (2.7.3)

MOT #10 2014-01-02 17:08

MOT test number 867892904087

Advice Nearside Steering rack gaiter deteriorated (2.2.D.2d)

Advice Nearside Inner Track rod end ball joint has slight play (2.2.B.1f)

CarCheck.co.uk page 8/18



MOT #9 2013-01-04 13:30

MOT test number 915034503099

Result ✓ Passed

Advice Nearside Front Lower Ball joint dust cover deteriorated, but preventing the ingress of dirt

(2.2.C.1c)

Advice Offside Front Brake pad(s) wearing thin (3.5.1g)

Notice Exhaust rear section outer skin deteriorated.

Advice Offside Front Lower Ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

Notice Power steering rack is damp with oil but has no visible leak.

MOT #8 2012-01-07 09:54

MOT test number 969807902082

Result Passed

Advice Offside Inner Drag link end ball joint has slight play (2.2.B.1f)

Advice Nearside Steering rack gaiter deteriorated (2.2.D.2d)

Notice Rear exhaust box deteriorated

MOT #7 2012-01-07 09:54

MOT test number 508807302038

Result X Failed

Advice Offside Inner Drag link end ball joint has slight play (2.2.B.1f)

Notice Rear exhaust box deteriorated

Advice Nearside Steering rack gaiter deteriorated (2.2.D.2d)

Pass with rectification Offside Front position lamp(s) not working (1.1.A.3b)

CarCheck.co.uk page 9/18



report date: 2024-03-29

MOT test number

S57334501036

Result

Notice Offside outer track rod end joint cover split/missing

Advice Rear Exhaust has part of the system slightly deteriorated (7.1.1a)

Advice Offside Inner Ball joint has slight play (2.2.B.1f)

MOT #5 2011-01-04 10:37 **MOT** test number 295344601019 Result × Failed Offside Registration plate lamp not working (1.1.C.1d) Fail Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1) **Notice** Requires wheel alignment check Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) **Advice** Offside Inner Ball joint has slight play (2.2.B.1f) **Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a) Notice Offside outer track rod end joint cover split/missing Fail Offside Front position lamp(s) not working (1.1.A.3b)

MOT #4		2010-01-05 11:52
MOT test	number	730865800003
Result		✓ Passed
Advice	Rear Exhaust has part of the system slightly deteriorated (7.1.1a)	
Notice	Oil leak	

CarCheck.co.uk page 10/18



report date: 2024-03-29

 MOT #3
 2008-12-30 11:27

 MOT test number
 621995968388

 Result
 ✓ Passed

 MOT #2
 2008-01-07 11:41

 MOT test number
 300357408039

 Result
 ✓ Passed

 Notice
 Slight play in steering rack o/s

MOT #1 2008-01-05 09:47 **MOT** test number 630265208042 Result × Failed **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1) Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1) **Notice** Slight play in steering rack o/s Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Nearside Steering rack gaiter split (2.2.D.2d)

CarCheck.co.uk page 11/18



See MOT history

Tax & MOT check

Full MOT history




CarCheck.co.uk page 12/18



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 13/18



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 14/18



Owner history

H747LNA

report date: 2024-03-29

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

See in this check if this NISSAN had different number plates.

More info >

More info >

CarCheck.co.uk page 15/18



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 16/18



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	1991-12-31
Last registration	2023-09-12
Complete history	See info



Registration #1	1991-12-31	29 mi
Registration #2	2008-01-05	34.757 mi
Registration #3	2008-01-07	55.924 mi
Registration #4	2008-12-30	37.834 mi
Registration #5	2010-01-05	40.234 mi
Registration #6	2011-01-04	70.533 mi
Registration #7	2011-01-04	70.533 mi
Registration #8	2012-01-07	74.053 mi
Registration #9	2013-01-04	80.765 mi
Registration #10	2014-01-02	88.101 mi
Registration #11	2014-12-23	96.029 mi
Registration #12	2016-01-08	99.144 mi
Registration #13		71.777 es
Registration #13 Registration #14		11.777 ea
		11.777 ea 11.777 ea 11.777 ea
Registration #14		11.777 ea 11.777 ea 11.777 ea
Registration #14 Registration #15		11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #14 Registration #15 Registration #16		11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #14 Registration #15 Registration #16 Registration #17		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		11,777 est
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea 11,777 ea
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		11,777 est

More info >



Car features

S0225	Air conditioning
50295	
60482	
60501	
60566	
60567	
60569	

Additional information

CarCheck.co.uk page 18/18