





report date: 2024-03-29

General information

Make	FORD
Model	C-MAX ZETEC 100
Colour	Blue
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-06-17

Pictures 10

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



Pass with rectification

EN10FVA

report date: 2024-03-29

MOT history

MOT #14		2022-06-08 14:02
MOT test	number	641792027563
Result		✓ Passed
Next expir	ry date	2023-06-09
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))	
Advice	Exhaust heat shield insecure	

MOT #13	2022-06-08 13:02
MOT test number	428751762712
Result	× Failed
Advice Exhaust heat shield insecure	
Advice Nearside Front Direction indicator slightly discoloured (4.4.3 (a))	
Fail Offside Rear Road wheel fixing loose (5.2.1 (a) (i))	

MOT #12	2021-06-10 11:35
MOT test number	857321870997
Result	✓ Passed
MOT #11	2021-06-10 11:35
MOT test number	458695233490
Result	× Failed
Pass with rectification lamps both (4.7.2 (a))	Registration plate lamp does not illuminate simultaneously with the position
Pass with rectification	Bonnet seriously at risk of opening inadvertently (3.1 (b) (ii))

MOT #10	2020-06-30 13:27
MOT test number	565047348183
Result	✓ Passed

Nearside Front Position lamp not working (4.2.1 (a) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #9 2019-07-29 12:43

MOT test number 468509720104

MOT #8 2019-07-25 08:08

MOT test number 487461227065

Result X Failed

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail Offside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #7 2018-07-25 14:50

MOT test number 791669509046

Result \rightarrow Passed

MOT #6 2018-07-25 09:48

MOT test number 736341497635

Result X Failed

Pass with rectification Nearside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Fail Offside Front Tyre tread depth below requirements of 1.6mm inner edge (5.2.3 (e))

Fail Offside Rear Tyre tread depth below requirements of 1.6mm inner edge (5.2.3 (e))

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm inner edge (5.2.3 (e))

MOT #5 2017-07-06 12:46

MOT test number 593566959225

Result

Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/11



report date: 2024-03-29

MOT #4 2016-07-30 09:48

MOT test number 856827337049

Result ✓ Passed

MOT #3 2015-07-13 11:34

MOT test number 235144695490

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #2 2014-07-18 13:53

MOT test number 797589694101

Result ✓ Passed

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Notice Vehicle's internal headlight adjuster altered to recheck lights

MOT #1 2013-07-23 10:32

MOT test number 399304803454

Result ✓ Passed

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Ov			L		4	
UN	wn	<u> </u>	n	9		rv

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report		ave?
THE PROPERTY OF THE PROPERTY O		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		
Current registration	NK NK	
Plate since		
Current registration	OK OK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-07-24
Last registration	2022-06-08
Complete history	See info



Registration #1	2010-07-24	7 mi
Registration #2	2013-07-23	11.666 mi
Registration #3	2014-07-18	23.310 mi
Registration #4	2015-07-13	39.266 mi
Registration #5	2016-07-30	55.116 mi
Registration #6	2017-07-06	67.508 mi
Registration #7	2018-07-25	83.408 mi
Registration #8	2018-07-25	83.414 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.177 es
Registration #15		11.777 es

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 10/11



Car features

S0225	Air conditionir
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1372 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	53
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number AL38072