





M

General information

| Make | MERCEDES-BENZ |
|---------------------|------------------|
| Model | SPRINTER 313 CDI |
| Colour | White |
| Year of manufacture | 2013 |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 129 BHP | 0 < 101 A |
|-----------------|----------|-------------------------------------|
| Engine capacity | 2.143 cc | 101 - 120 ^B _C |
| Cylinders | 4 | 121 - 140 P |
| Fuel type | Diesel | 141 - 165 ^F _G |
| CO2 emission | 202 g/km | 166 - 185 H |
| CO2 label | К | 186 - 225 J |
| | | 225+ L |





Internet history

Entry 2

Date Pictures 2023-01-20

20

Listing price

View report



source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

2022-06-13 21

View report



source: cargurus.co.uk









MOT history

| MOT expiry date | 2024-12-13 |
|--------------------|------------|
| MOT pass rate | 70 % |
| MOT passed | 7 |
| Failed MOT tests | 3 |
| Total advice items | 14 |
| Total items failed | 12 |

| MOT #10 | | 2023-12-14 12:09 |
|-----------|--|-------------------------|
| MOT test | number | 334573529324 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-12-13 |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened both | sides (1.1.14 (a) (ii)) |
| Advice | Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii)) | |
| Advice | Front Brake disc worn, pitted or scored, but not seriously weakened both | sides (1.1.14 (a) (ii)) |
| Advice | Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii)) | |

MOT #9 2022-06-09 13:10 **MOT test number** 281923062364 Result ✓ Passed Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Power steering fluid level below minimum (2.1.5 (b) (i)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Front Windscreen wiper blade defective (3.4 (b) (i)) Minor Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))





| MOT #8 | | 2020-11-19 08:10 |
|-------------------------|--|------------------|
| MOT test number | | 208436025343 |
| Result | | ✓ Passed |
| | | |
| MOT #7 | | 2020-11-19 08:10 |
| MOT test number | | 416350503908 |
| Result | | 🗙 Failed |
| | | |
| Pass with rectification | Offside Front Headlamp aim too low (4.1.2 (a)) | |
| Pass with rectification | Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) | |
| | | |

| MOT #6 | 2019-11-25 06:43 |
|-----------------|------------------|
| MOT test number | 261262426027 |
| Result | ✓ Passed |

| MOT #! | 5 | 2019-11-19 16:25 |
|--------|--|------------------|
| MOT te | st number | 925636722468 |
| Result | | 🗙 Failed |
| Fail | Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 | (c)) |
| Fail | Front Registration plate insecure (0.1 (a)) | |
| Fail | Brake slack adjuster has restricted free movement (1.1.15 (e)) | |
| Mino | r Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning | (4.2.1 (a) (i)) |
| Fail | Brake pipe excessively corroded Both front to rear (1.1.11 (c)) | |

| MOT #4 | | 2018-11-20 08:30 |
|--------------|--|------------------|
| MOT test nun | mber | 229240020966 |
| Result | | ✓ Passed |
| Advice Br | rake pipe corroded, covered in grease or other material Both Front To Rear | (1.1.11 (c)) |



DG63MYV report date: 2024-03-28

| MOT #3 | 2018-11-16 16:25 |
|---|------------------|
| MOT test number | 716347762179 |
| Result | 🗙 Failed |
| Fail Exhaust system insecure dpf bracket snapped (6.1.2 (a)) | |
| Fail Brake slack adjuster has restricted free movement Compensator (1.1.15 (e)) | |
| Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |
| Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) | |
| Advice Brake pipe corroded, covered in grease or other material Both Front To Rear (1 | l.1.11 (c)) |
| Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) | |
| Fail Offside Rear Position lamp not working (4.2.1 (a)) | |

| MOT #2 | 2017-11-24 16:17 |
|-----------------|------------------|
| MOT test number | 579713687528 |
| Result | ✓ Passed |

| MOT #1 | | 2016-11-08 09:17 |
|----------|--|------------------|
| MOT test | number | 819400474605 |
| Result | | ✓ Passed |
| Advice | Play in steering rack inner joint(s) both sides | |
| Advice | Parking brake lever has little reserve travel (3.1.6b) | |





Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | |
| Category | L'ERNPE |
| Туре | |
| Damage 2 | AMPLE |
| | E Store |
| Date | L. |
| Category | AMPL |
| Туре | |

Extra MERCEDES-BENZ salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|--|-------------|
| | |
| | |
| ******** | |
| | |
| And a second sec | |
| ********** | |
| ******** | |
| | |
| | More info > |
| | |
| Plate changes | |
| See in this check if this MERCEDES-BENZ had different number plates. | |
| | |
| Number of plates | |
| | |
| Current registration | |
| Plate since | 10003.03.00 |
| | |
| Current registration | |
| Plate since | |
| | |
| | |





Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 13 |
| First mileage registration | 2013-12-06 |
| Last registration | 2023-12-14 |
| Complete history | <u>See info</u> |



| Registration #1 | 2013-12-06 | 22 mi |
|------------------|------------|------------|
| Registration #2 | 2016-11-08 | 76.737 mi |
| Registration #3 | 2017-11-24 | 100.915 mi |
| Registration #4 | 2018-11-16 | 122.457 mi |
| Registration #5 | 2018-11-20 | 122.457 mi |
| Registration #6 | 2019-11-19 | 145.513 mi |
| Registration #7 | 2019-11-25 | 145.513 mi |
| Registration #8 | | 11.117 esi |
| Registration #9 | | 11.117 esi |
| Registration #10 | | 11.117 esi |
| Registration #11 | | 11.117 esi |
| Registration #12 | | 11.777 est |
| Registration #13 | | 11.117 mi |

More info \rightarrow





Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| 50482 | |
| \$0501 | |
| S0566 | |
| \$0567 | |
| S0569 | |

Dimensions & weight

| Width | 1993 mm |
|---------------------|---------|
| Height | 2350 mm |
| Length | 5870 mm |
| Kerb weight | 1842 kg |
| Max. allowed weight | 3500 kg |

Additional information

| Fuel delivery | Direct Injection |
|-----------------|------------------|
| Number of doors | 2 |
| Number of seats | 3 |
| Engine number | 65195531890799 |