



report date: 2024-03-28

General information

Make	MINI
Model	COOPER SD AUTO COOPER SD
Colour	Black
Year of manufacture	2013
Top speed	128 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	141 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.9 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-02
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2023-03-07
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	12
Total items failed	1

MOT #8 2022-02-22 13:46

MOT test number 198552034069

Result ✓ Passed

Next expiry date 2023-03-07

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Tyre slightly damaged/cracking or perishing n/s & o/s (5.2.3 (d) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Tyre worn close to legal limit/worn on edge n/s & o/s (5.2.3 (e))

MOT #7 2021-03-08 15:05

MOT test number 958399476853

Result ✓ Passed

MOT #6 2020-09-07 13:03

MOT test number 148175284679

Result ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing between treads (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing between treads (5.2.3 (d) (ii))

**MOT #5** 2019-09-12 09:10**MOT test number** 404704620845**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2018-09-08 09:40**MOT test number** 518849980567**Result** ✓ Passed**MOT #3** 2018-09-07 09:11**MOT test number** 772920313659**Result** ✗ Failed**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #2** 2017-08-29 14:23**MOT test number** 158991287479**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2016-09-20 10:16**MOT test number** 766736821020**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
31 January 2023

X

MOT

Expired:  
7 March 2023

Tax status	Expired at 31 January 2023
Days left	455 days too late
MOT expiry date	7 March 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2013-09-27
Last registration	2022-02-22
Complete history	<a href="#">See info</a>



Registration #1	2013-09-27	28 mi
Registration #2	2016-09-20	20.996 mi
Registration #3	2017-08-29	30.566 mi
Registration #4	2018-09-07	38.551 mi
Registration #5	2018-09-08	38.551 mi
Registration #6	2019-09-20	38.551 mi
Registration #7	2019-09-20	38.551 mi
Registration #8	2019-09-20	38.551 mi
Registration #9	2019-09-20	38.551 mi
Registration #10	2019-09-20	38.551 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1384 mm
Length	3734 mm
Wheel base	2467 mm
Kerb weight	1195 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2

Number of axles	2
Engine number	72548552