



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	TIGUAN S TDI 4MOTION
Colour	Silver
Year of manufacture	2008
Top speed	116 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.1 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	182 g/km
CO2 label	I






Internet history

Entry 2

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-01-29
Pictures	11
Listing price	View report



source: [yesauto.com](#)



MOT history

MOT expiry date	2025-03-12
MOT pass rate	78 %
MOT passed	14
Failed MOT tests	4
Total advice items	23
Total items failed	6

MOT #182024-03-13 09:04

MOT test number129080785833

Result✓ Passed

Next expiry date2025-03-12

- Advice

Exhaust noisy (8.1.1 (a))
- Advice

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))
- Minor

Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice

Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))
- Advice

Both front brake dust plates corroded

**MOT #17**

2024-03-05 12:18

MOT test number

193048519655

Result

✗ Failed

Minor

Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail

Central Rear Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

Advice

Both front brake dust plates corroded

Fail

Offside Front Direction indicator incorrect colour (4.4.3 (a))

Advice

Exhaust noisy (8.1.1 (a))

Advice

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

Fail

Nearside Front Direction indicator incorrect colour (4.4.3 (a))

Advice

Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #16

2023-02-08 15:12

MOT test number

670914455966

Result

✓ Passed

Advice

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

Advice

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

MOT #15

2023-02-08 10:04

MOT test number

213323608334

Result

✗ Failed

Advice Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

**MOT #14** 2022-01-17 09:36**MOT test number** 499267333372**Result** ✓ Passed**MOT #13** 2021-02-11 16:55**MOT test number** 745577979433**Result** ✓ Passed**MOT #12** 2019-09-30 11:34**MOT test number** 420902017016**Result** ✓ Passed**MOT #11** 2018-11-27 14:11**MOT test number** 549294897555**Result** ✓ Passed**MOT #10** 2017-12-04 14:48**MOT test number** 979195517755**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2017-07-14 14:38**MOT test number** 107199287190**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2017-07-12 13:34**MOT test number** 613401080924**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #7** 2016-07-08 11:08**MOT test number** 297701573166**Result** ✓ Passed**Advice** Emissions to low too test**MOT #6** 2016-07-08 11:06**MOT test number** 146853231968**Result** ✗ Failed**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Emissions to low too test**MOT #5** 2015-07-16 11:50**MOT test number** 166037095164**Result** ✓ Passed**MOT #4** 2014-07-09 12:15**MOT test number** 116960894114**Result** ✓ Passed**MOT #3** 2013-07-10 11:41**MOT test number** 486361293183**Result** ✓ Passed



MOT #2	2012-07-18 15:09
MOT test number	337610102441
Result	✓ Passed

MOT #1	2011-07-18 11:56
MOT test number	129919691188
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
12 March 2025

Tax status	Valid until 1 August
Days left	95
MOT expiry date	12 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-07-10
Last registration	2024-03-13
Complete history	See info



Registration #1	2008-07-10	20 mi
Registration #2	2011-07-18	21.797 mi
Registration #3	2012-07-18	31.125 mi
Registration #4	2013-07-10	40.781 mi
Registration #5	2014-07-09	48.838 mi
Registration #6	2015-07-16	57.391 mi
Registration #7	2016-07-08	66.294 mi
Registration #8	2016-07-08	66.294 mi
Registration #9	2017-07-12	72.578 mi
Registration #10	2017-07-14	72.589 mi
Registration #11	2017-12-04	74.703 mi
Registration #12	2018-01-01	75.000 mi
Registration #13	2018-01-01	75.000 mi
Registration #14	2018-01-01	75.000 mi
Registration #15	2018-01-01	75.000 mi
Registration #16	2018-01-01	75.000 mi
Registration #17	2018-01-01	75.000 mi
Registration #18	2018-01-01	75.000 mi
Registration #19	2018-01-01	75.000 mi
Registration #20	2018-01-01	75.000 mi
Registration #21	2018-01-01	75.000 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1809 mm
Height	1686 mm
Length	4427 mm
Wheel base	2604 mm
Kerb weight	1590 kg
Max. allowed weight	2240 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	CBA 263304