



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 D R-DESIGN
Colour	Silver
Year of manufacture	2010
Top speed	127 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	151 g/km
CO2 label	G








Internet history

Entry 2

Date	2024-03-12
Pictures	29
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)

Entry 1

Date	2021-12-18
Pictures	50
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)



MOT history

MOT expiry date	2025-04-22
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	25
Total items failed	5

MOT #14	2024-04-23 13:49
MOT test number	389075555928
Result	✓ Passed
Next expiry date	2025-04-22

MOT #13	2023-11-01 11:06
MOT test number	185066992789
Result	✓ Passed
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2022-11-01 09:33
MOT test number	566497897597
Result	✓ Passed
Advice	Undertrays fitted not allowing full inspection
Advice	Engine covers fitted not allowing full inspection

**MOT #11** 2021-11-18 10:51**MOT test number** 919805333171**Result** ✓ Passed

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #10** 2021-11-02 13:17**MOT test number** 572948964660**Result** ✗ Failed

**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))

**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #9** 2020-11-09 15:40**MOT test number** 769133050606**Result** ✓ Passed**MOT #8** 2019-10-05 08:03**MOT test number** 177133959568**Result** ✓ Passed

**Advice** Nearside Rear Nail in the tyre

**Advice** Emission too clean to record

**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner and outer edges (5.2.3 (e))

**MOT #7**

2019-10-05 08:03

**MOT test number**

153875012909

**Result**

✗ Failed

**Pass with rectification** Offside Front Headlamp aim too high (4.1.2 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner and outer edges (5.2.3 (e))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**Advice** Emission too clean to record**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Nail in the tyre**MOT #6**

2018-10-06 08:34

**MOT test number**

683497263398

**Result**

✓ Passed

**Advice** Engine covers and under trays fitted at time of test**MOT #5**

2017-10-16 09:01

**MOT test number**

889034003326

**Result**

✓ Passed

**Advice** Engine covers fitted at time of test**Advice** Offside Rear Tyre worn close to the legal limit 205/50r17 (4.1.E.1)**Advice** Under trays fitted at time of test**MOT #4**

2016-09-29 09:59

**MOT test number**

843832001579

**Result**

✓ Passed

**MOT #3** 2015-09-21 12:24**MOT test number** 955349162048**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2014-09-27 10:59**MOT test number** 285110174254**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2013-10-15 09:20**MOT test number** 325778683478**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
10 March 2024

✓

MOT

Expires:  
22 April 2025

Tax status	Expired at 10 March 2024
Days left	50 days too late
MOT expiry date	22 April 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-10-19
Last registration	2024-04-23
Complete history	<a href="#">See info</a>



Registration #1	2010-10-19	17 mi
Registration #2	2013-10-15	19.942 mi
Registration #3	2014-09-27	27.293 mi
Registration #4	2015-09-21	34.503 mi
Registration #5	2016-09-29	39.824 mi
Registration #6	2017-10-16	44.301 mi
Registration #7	2018-10-06	46.399 mi
Registration #8	2019-10-05	48.189 mi
Registration #9	2019-10-05	48.189 mi
Registration #10	2020-10-05	50.000 mi
Registration #11	2021-10-05	52.000 mi
Registration #12	2022-10-05	54.000 mi
Registration #13	2023-10-05	56.000 mi
Registration #14	2024-04-23	58.000 mi
Registration #15	2024-04-23	58.000 mi
Registration #16	2024-04-23	58.000 mi
Registration #17	2024-04-23	58.000 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1430 kg
Max. allowed weight	1840 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	746796