





report date: 2024-03-29

General information

| Make | CITROEN |
|---------------------|----------------------------------------------------|
| Model | GRAND C4 PICASSO HDI VTR PLUS EGS GRAND PICASSO |
| Colour | Red |
| Year of manufacture | 2011 |
| Top speed | 113 mph |
| 0 - 60 mph | 13.5 seconds |
| Gearbox | 6 speed Semi-Automatic |

Engine & fuel consumption

| Power | 110 BHP |
|-------------------------|---------------------|
| Max. torque | 285 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 47.1 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 54.3 mpg |
| CO2 emission | 136 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2021-07-26

Pictures 8

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



MOT history

| MOT expiry date | 2024-09-25 |
|--------------------|------------|
| MOT pass rate | 69 % |
| MOT passed | 11 |
| Failed MOT tests | 5 |
| Total advice items | 24 |
| Total items failed | 11 |

| MOT #16 | 2023-09-26 14:21 |
|--------------------------------------------------------------------------------------------------------|------------------|
| MOT test number | 700504294890 |
| Result | ✓ Passed |
| Next expiry date 2024-09-2 | |
| Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii)) | |

| MOT #15 | 2023-09-13 10:37 | |
|--------------------------------------------------------------------------------------------------------|------------------|--|
| MOT test number | 104992500439 | |
| Result | X Failed | |
| Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii)) | | |
| Fail Brake pad(s) less than 1.5 mm thick All ROUND (1.1.13 (a) (ii)) | | |
| Fail Nearside Obligatory mirror insecure (3.3 (b) (ii)) | | |
| Minor Rear Registration plate lamp throwing direct white light to the rear Both lam | ps (4.7.1 (a)) | |

| MOT #14 | 2022-09-12 09:53 |
|-----------------------------------------------------------------------------------|------------------|
| MOT test number | 552829000751 |
| Result | ✓ Passed |
| Minor Registration plate lamp throwing direct white light to the rear (4.7.1 (a)) | |

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT test number
760582535085

Result

Fail Electronic parking brake control defective so that it cannot be satisfactorily operated (1.1.6 (d))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Electronic braking system warning device inoperative (1.7 (a))

Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

 MOT #12
 2021-08-10 10:11

 MOT test number
 584977387408

 Result
 ✓ Passed

 MOT #11
 2021-08-09 15:19

 MOT test number
 286663129812

 Result
 X Failed

 Fail
 Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

MOT test number

Result

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Drag link end ball joint has slight play rack arm (2.1.3 (b) (i))

MOT #8 2018-12-03 16:19

MOT test number 947656946398

Result ✓ Passed

MOT test number

Result

Pass with rectification

Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Pass with rectification

Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT test number

Segult

Result

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Cannot obtain an emissions reading

Advice

Offside Rear Child Seat fitted not allowing full inspection of adult belt

Under trays fitted obscuring some components

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #5 2018-01-17 08:52 560178262997 **MOT** test number Result × Failed **Advice** Cannot obtain an emissions reading Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt Pass with rectification Offside Rear Direction indicator incorrect colour (1.4.A.2f) Advice Under trays fitted obscuring some components Pass with rectification Nearside Rear Direction indicator incorrect colour (1.4.A.2f) **Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Rear Child Seat fitted not allowing full inspection of adult belt

Rear Child Seat fitted not allowing full inspection of adult belt

| MOT #3 | | 2016-02-04 09:50 |
|----------|----------------------------------------------------------------|------------------|
| MOT test | number | 343461191413 |
| Result | | ✓ Passed |
| Advice | Engine covers and under trays fitted obscuring some components | |
| Advice | Wiper blades deteriorating | |
| Advice | Child seats fitted unable to fully check rear seat belts | |

CarCheck.co.uk page 6/14



MOT #2

MOT test number

976273445003

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

 MOT #1
 2014-07-17 11:35

 MOT test number
 377918394157

 Result
 ✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check





Expires: 25 September 2024

| Tax status | Valid until 1 April |
|------------------|---------------------|
| Days left | 336 |
| MOT expiry date | 25 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|-----------------------------------------|------------|
| Band | Е |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

More info >

| Owner history | |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|
| For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full | |
| ********* | |
| *************************************** | |
| *************************************** | |
| ********* | |
| | |
| ************ | |
| Dista changes | More info > |
| Plate changes See in this check if this CITROEN had different number plates. | |
| Number of plates | |
| Current registration | NK SIE |
| Plate since | |
| Current registration | NK NY |
| Plate since | |

CarCheck.co.uk page 11/14



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Courts at info | |

Contact info

More info >

CarCheck.co.uk page 12/14




V061LMU

report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 18 |
| First mileage registration | 2011-09-19 |
| Last registration | 2023-09-26 |
| Complete history | See info |



| Registration #1 | 2011-09-19 | 23 mi |
|------------------|------------|-----------|
| Registration #2 | 2014-07-17 | 21.383 mi |
| Registration #3 | 2015-02-12 | 23.368 mi |
| Registration #4 | 2016-02-04 | 38.062 mi |
| Registration #5 | 2017-01-24 | 52.655 mi |
| Registration #6 | 2018-01-17 | 66.643 mi |
| Registration #7 | 2018-01-17 | 66.643 mi |
| Registration #8 | 2018-12-03 | 79.255 mi |
| Registration #9 | 2018-12-03 | 79.255 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 11.777 es |
| Registration #16 | | 11.777 es |
| Registration #17 | | 11.777 es |
| Registration #18 | | 11.117 es |

More info >

CarCheck.co.uk page 13/14



Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 90% |
| Children | 85% |
| Pedestrian | 43% |
| Safety systems | 97% |
| Overall rating | 80% |
| Video | see crash video |



Dimensions & weight

| Width | 1830 mm |
|---------------------|---------|
| Height | 1710 mm |
| Length | 4590 mm |
| Wheel base | 2728 mm |
| Kerb weight | 1539 kg |
| Max. allowed weight | 2250 kg |

Additional information

| Fuel tank capacity | 60 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 7 |
| Number of axles | 2 |
| Engine number | JBCJ3102459 |

CarCheck.co.uk page 14/14