





report date: 2024-03-29

General information

Make	MAZDA
Model	5 TS2
Colour	Grey
Year of manufacture	2007
Top speed	121 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.999 сс
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	42.8 mpg
Consumption combined	34.5 mpg
CO2 emission	198 g/km
CO2 label	J



CarCheck.co.uk page 1/14



report date: 2024-03-29


Internet history

Entry 1

Date 2021-08-10

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT expiry date	2024-11-02
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	17
Total items failed	14

MOT #20	2023-11-03 12:59
MOT test number	628788058020
Result	✓ Passed
Next expiry date	2024-11-02
Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #19	2023-11-03 12:47
MOT test number	451766756234
Result	X Failed
Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

MOT #18		2022-09-02 12:19
MOT test	number	373879222162
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords	s (5.2.3 (d) (i))

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #17 2021-08-09 15:27

MOT test number 803024088584

Result ✓ Passed

MOT #16 2021-08-04 16:18

MOT test number 170916828512

Result X Failed

Fail Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Fail Exhaust shield missing where fitted as original equipment creating a risk of fire near petrol tank (6.1.3 (e))

MOT #15 2020-08-21 10:52

MOT test number 311623913575

Result \rightarrow Passed

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #14 2020-08-20 09:23

MOT test number 667974219908

Result X Failed

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Fail Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #13 2019-07-25 14:42

MOT test number 430879435494

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #12 2018-07-27 09:42

MOT test number 252318347887

Result ✓ Passed

MOT #11 2017-04-25 17:17

MOT test number 505352967107

Result \rightarrow Passed

MOT #10 2016-07-01 15:31

MOT test number 951620436774

Result \rightarrow Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #9 2016-07-01 07:59

MOT test number 410498223124

Result × Failed

Fail Nearside Headlamp not working on dipped beam (1.7.5a)

Advice Front Brake pad(s) wearing thin (3.5.1g)

Fail Rear fog lamp insecure (1.3.2a)

Fail Offside Rear coil spring broken (2.4.C.1a)

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #8 2015-08-01 09:45

MOT test number 868033615295

Result ✓ Passed

MOT #7 2015-07-31 08:16

MOT test number 219592915292

Result X Failed

Fail Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

Fail Nearside Headlamp aim too high (1.8)

Fail Nearside Rear Shock absorber has a serious fluid leak (2.7.3)

Fail Offside Rear fog lamp not working (1.3.2b)

Notice REAR TYRES WEARING SMOOTH ON EDGES CLOSE TO LIMIT AT TIME OF TEST

Fail Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)

Fail Offside Headlamp aim too high (1.8)

MOT #6 2014-07-02 12:27

MOT test number 279003584495

Result / Passed

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #5 2013-07-05 09:25

MOT test number 958176883197

Result
✓ Passed

MOT #4 2012-07-04 11:10

MOT test number 997646382114

Result ✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #3	2011-07-01 14:58
MOT test number	585562081127
Result	✓ Passed
MOT #2	2010-07-01 14:57
MOT test number	313722780104
Result	✓ Passed
MOT #1	2010-06-30 08:39
MOT test number	284141180168
Result	× Failed
Fail Offside Rear Shock absorber has a serious fluid leak (2.7.3)	

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	2 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



faste since

WD07CYG

report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this MAZDA had different number plates. ober of plates

More info >



report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-06-29
Last registration	2023-11-03
Complete history	See info



Registration #1	2007-06-29	8 mi
Registration #2	2010-06-30	30.800 mi
Registration #3	2010-07-01	30.820 mi
Registration #4	2011-07-01	39.880 mi
Registration #5	2012-07-04	51.018 mi
Registration #6	2013-07-05	61.111 mi
Registration #7	2014-07-02	65.978 mi
Registration #8	2015-07-31	77.137 mi
Registration #9	2015-08-01	77.137 mi
Registration #10	2016-07-01	95.508 mi
Registration #11	2016-07-01	95.509 mi
Registration #12		71.777 es
Registration #13		11.117 es
Registration #14		71.777 es
Registration #15		11.117 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.117 es
Registration #19		11.177 es
Registration #20		11.777 es
Registration #21		11,777 es
Registration #22		11.777 es

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4420 mm
Wheel base	2750 mm
Kerb weight	1527 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	LF 10206761

CarCheck.co.uk page 14/14