



HYUNDAI




report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX20 CLASSIC
Colour	White
Year of manufacture	2012
Top speed	104 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	50.4 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-06-18
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-06
MOT pass rate	59 %
MOT passed	10
Failed MOT tests	7
Total advice items	41
Total items failed	4

MOT #17	2023-09-05 12:59
MOT test number	870673226168
Result	✓ Passed
Next expiry date	2024-09-06
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #16	2022-08-11 11:39
MOT test number	970635410209
Result	✓ Passed

MOT #15	2022-08-11 11:39
MOT test number	890372804056
Result	✗ Failed
Pass with rectification	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #14** 2021-09-07 10:23**MOT test number** 674672625892**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**MOT #13** 2021-09-06 15:35**MOT test number** 268192436032**Result** ✗ Failed**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**MOT #12** 2021-03-11 15:26**MOT test number** 157742329675**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Play in steering rack inner joint(s) both sides**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #11**

2021-03-04 14:00

MOT test number

544232372716

Result**✗ Failed**

- MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))
- MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Play in steering rack inner joint(s) both sides
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10

2020-03-05 16:57

MOT test number

413873910981

Result**✓ Passed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner shoulder is worn (5.2.3 (e))
- Advice** Play in steering rack inner joint(s) both sides
- Advice** Offside Front Tyre worn close to legal limit/worn on edge inner shoulder is worn (5.2.3 (e))

**MOT #9** 2020-03-03 17:01**MOT test number** 265320002107**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner shoulder is worn (5.2.3 (e))**MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner shoulder is worn (5.2.3 (e))**Advice** Play in steering rack inner joint(s) both sides**MAJOR** Rear Registration plate inscription illegible (0.1 (b))**MAJOR** Nearside Side repeater not working (4.4.1 (a) (ii))**MOT #8** 2019-03-05 14:59**MOT test number** 331198654176**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2018-02-26 15:58**MOT test number** 308515293220**Result** ✓ Passed**MOT #6** 2018-02-26 15:36**MOT test number** 894407297907**Result** ✗ Failed**Fail** Central Rear Seat belt locking mechanism does not secure or release unable to locate correct stalk , due to baby seat (5.2.5a)

**MOT #5** 2017-03-07 00:31**MOT test number** 356063087040**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front Tyre worn close to the legal limit Both (4.1.E.1)**MOT #4** 2016-02-29 15:46**MOT test number** 168725237434**Result** ✓ Passed**MOT #3** 2016-02-29 14:12**MOT test number** 767511295168**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2015-03-06 16:21**MOT test number** 967455765024**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)



MOT #1

2015-03-06 11:42

MOT test number

739285665021

Result

✗ Failed

- Advice

Offside Rear Shock absorber has a light misting of oil (2.7.3)
- Advice

Rear Brake pad(s) wearing thin (3.5.1g)
- Fail

Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice

Front Brake pad(s) wearing thin (3.5.1g)
- Notice

Both rear tyres cracking in tread



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
6 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	6 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	BF12SJU
Plate since	2019-03-28
Current registration	BF12SJU
Plate since	2019-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2012-03-08
Last registration	2023-09-05
Complete history	See info



Registration #1	2012-03-08	17 mi
Registration #2	2015-03-06	42.709 mi
Registration #3	2015-03-06	42.709 mi
Registration #4	2016-02-29	55.159 mi
Registration #5	2016-02-29	55.159 mi
Registration #6	2017-03-07	61.591 mi
Registration #7	2018-02-26	69.731 mi
Registration #8	2018-02-26	69.731 mi
Registration #9	2019-03-05	78.541 mi
Registration #10	2020-03-03	86.012 mi
Registration #11	2020-03-03	86.012 mi
Registration #12	2020-03-03	86.012 mi
Registration #13	2020-03-03	86.012 mi
Registration #14	2020-03-03	86.012 mi
Registration #15	2020-03-03	86.012 mi
Registration #16	2020-03-03	86.012 mi
Registration #17	2020-03-03	86.012 mi
Registration #18	2020-03-03	86.012 mi
Registration #19	2020-03-03	86.012 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1268 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4FACZ519415