



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	307 COUPE CABRIOLET
Colour	Maroon
Year of manufacture	2004
Top speed	127 mph
0 - 60 mph	12.0 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	190 Nm at 4.100 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.6 mpg
Consumption extra urban	42.8 mpg
Consumption combined	31.7 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-07-15
Pictures	9
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-02-04
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	46
Total items failed	24

MOT #23	2024-02-05 15:31
MOT test number	740363170458
Result	✓ Passed
Next expiry date	2025-02-04
Advice	Offside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))
Advice	Offside Front Play in steering rack inner joint(s)
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))
Advice	Front Brake disc worn, but not excessively Both. Inner face (1.1.14 (a) (i))
Advice	Nearside Front Play in steering rack inner joint(s)

**MOT #22**

2024-02-05 15:31

MOT test number

257959625288

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))
- Pass with rectification** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Inner edge (5.2.3 (e))
- Pass with rectification** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Front Brake disc worn, but not excessively Both. Inner face (1.1.14 (a) (i))
- Advice** Nearside Front Play in steering rack inner joint(s)

MOT #21

2023-01-31 10:40

MOT test number

133435993095

Result**✓ Passed**

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #20**

2023-01-25 10:52

MOT test number

220772695929

Result**✗ Failed**

- Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Front Windscreen washer not working (3.5 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Front Side repeater not working (4.4.1 (a) (ii))
- Advice** Rear Exhaust silencer slightly loose (8.1.1 (b) (i))
- Advice** Offside Front Play in steering rack inner joint(s)
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**MOT #19**

2023-01-10 17:10

MOT test number

362870021407

Result**✗ Failed**

- Advice** Nearside Play in steering rack inner joint(s)
- Fail** Emissions not tested Due to exhaust leak (8.2.1.2 (d))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened Corroded (1.1.14 (a) (ii))
- Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Both bushes are cracking (5.3.4 (a) (i))
- Fail** Central Exhaust has a major leak of exhaust gases And rear (6.1.2 (a))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Insecure (6.1.7 (g) (ii))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Corroded (1.1.14 (a) (ii))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Rear Tyre worn close to legal limit/worn on edge Both wearing on edges (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Offside Headlamp aim too low (4.1.2 (a))

MOT #18

2022-01-10 15:23

MOT test number

699766581652

Result**✓ Passed**

- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17** 2021-11-18 15:14**MOT test number** 775915763783**Result** ✗ Failed

- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Offside Windscreen washer not working (3.5 (a))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Windscreen washer not working (3.5 (a))
- Fail** Offside Headlamp aim too high (4.1.2 (a))

MOT #16 2020-11-23 16:57**MOT test number** 317442076088**Result** ✓ Passed

- Advice** Offside Play in steering rack inner joint(s)
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #15 2019-10-08 10:43**MOT test number** 595929758108**Result** ✓ Passed**MOT #14** 2018-10-03 13:47**MOT test number** 452037897047**Result** ✓ Passed**MOT #13** 2017-10-04 08:12**MOT test number** 586243632030**Result** ✓ Passed

**MOT #12** 2016-10-04 09:32**MOT test number** 500116633779**Result** ✓ Passed**MOT #11** 2015-09-29 16:51**MOT test number** 640706968714**Result** ✓ Passed**MOT #10** 2015-09-29 13:28**MOT test number** 843316991048**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear wheel bearing rough when rotated (2.6.1)**MOT #9** 2014-10-06 09:16**MOT test number** 119599174222**Result** ✓ Passed**MOT #8** 2013-10-04 14:00**MOT test number** 115147073225**Result** ✓ Passed**Notice** N/s/rear tyre wearing outer edge**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2012-10-05 17:09**MOT test number** 956179572203**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2012-10-05 10:43**MOT test number** 989209672253**Result** ✗ Failed**Fail** Exhaust tailpipe not capable of allowing the emission probe to be inserted (7.3.D.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Rear Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-10-05 06:35**MOT test number** 229098371201**Result** ✓ Passed**Notice** Nail in offside front tyre**MOT #4** 2010-10-05 12:55**MOT test number** 383668770226**Result** ✓ Passed**MOT #3** 2009-10-08 10:38**MOT test number** 541191789209**Result** ✓ Passed**Notice** Front brake check suspect pads getting low**Advice** Offside Inner Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2008-10-08 12:25**MOT test number** 691722088258**Result** ✓ Passed



MOT #1	2007-10-12 15:40
MOT test number	304485187482
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
4 February 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	4 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-08-12
Last registration	2024-02-05
Complete history	See info



Registration #1	2004-08-12	25 mi
Registration #2	2007-10-12	22.584 mi
Registration #3	2008-10-08	24.390 mi
Registration #4	2009-10-08	25.764 mi
Registration #5	2010-10-05	27.273 mi
Registration #6	2011-10-05	28.758 mi
Registration #7	2012-10-05	30.074 mi
Registration #8	2012-10-05	30.074 mi
Registration #9	2013-10-04	31.283 mi
Registration #10	2014-10-06	32.408 mi
Registration #11	2015-09-29	33.614 mi
Registration #12	2015-09-29	33.615 mi
Registration #13	2016-10-04	34.739 mi
Registration #14	2016-10-04	34.739 mi
Registration #15	2016-10-04	34.739 mi
Registration #16	2016-10-04	34.739 mi
Registration #17	2016-10-04	34.739 mi
Registration #18	2016-10-04	34.739 mi
Registration #19	2016-10-04	34.739 mi
Registration #20	2016-10-04	34.739 mi
Registration #21	2016-10-04	34.739 mi
Registration #22	2016-10-04	34.739 mi
Registration #23	2016-10-04	34.739 mi
Registration #24	2016-10-04	34.739 mi
Registration #25	2016-10-04	34.739 mi



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1423 mm
Length	4349 mm
Wheel base	2605 mm
Kerb weight	1488 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	LH1L1007649