



report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 SE LUX AWD
Colour	Black
Year of manufacture	2011
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	200 BHP
Max. torque	420 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.7 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.0 mpg
CO2 emission	219 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-06
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-15
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	24
Total items failed	5

MOT #16	2024-03-08 09:28
MOT test number	606572309262
Result	✓ Passed
Next expiry date	2025-03-15
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #15	2023-03-16 09:38
MOT test number	613683898714
Result	✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #14	2022-03-04 15:31
MOT test number	591941014806
Result	✓ Passed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13** 2022-02-28 09:30**MOT test number** 682704806832**Result** ✗ Failed**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2021-03-04 17:14**MOT test number** 424844041557**Result** ✓ Passed**MOT #11** 2020-02-25 14:21**MOT test number** 955894772705**Result** ✓ Passed**MOT #10** 2020-02-24 09:38**MOT test number** 388529931958**Result** ✗ Failed**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**DANGEROUS** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #9** 2019-02-15 12:01**MOT test number** 101370751928**Result** ✓ Passed

- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inside edge (1.1.14 (a) (ii))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn low on inside edge (5.2.3 (e))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inside edge (1.1.14 (a) (ii))

MOT #8 2019-02-15 12:01**MOT test number** 946271893719**Result** ✗ Failed

- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inside edge (1.1.14 (a) (ii))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn low on inside edge (5.2.3 (e))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inside edge (1.1.14 (a) (ii))
- Pass with rectification** Offside Front Outline marker lamp not working (4.2.1 (a))

MOT #7 2018-02-26 11:05**MOT test number** 949755922037**Result** ✓ Passed

**MOT #6** 2018-02-26 11:05**MOT test number** 535756993569**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #5** 2017-02-27 10:33**MOT test number** 268359772386**Result** ✓ Passed**MOT #4** 2017-02-27 10:33**MOT test number** 781605051409**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**Pass with rectification** Nearside Headlamp aim too low (1.8)**MOT #3** 2016-03-15 11:50**MOT test number** 941101928319**Result** ✓ Passed**MOT #2** 2015-03-06 11:38**MOT test number** 788505265008**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2014-04-11 16:08**MOT test number** 269041504427**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
15 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	15 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	RE11CZC
Plate since	2024-03-29
Current registration	RE11CZC
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-04-19
Last registration	2024-03-08
Complete history	See info



Registration #1	2011-04-19	6 mi
Registration #2	2014-04-11	38.623 mi
Registration #3	2015-03-06	50.542 mi
Registration #4	2016-03-15	60.549 mi
Registration #5	2017-02-27	69.264 mi
Registration #6	2017-02-27	69.264 mi
Registration #7	2018-02-26	78.016 mi
Registration #8	2018-02-26	78.016 mi
Registration #9	2019-02-15	89.633 mi
Registration #10	2019-03-20	95.377 mi
Registration #11	2019-03-20	95.377 mi
Registration #12	2019-03-20	95.377 mi
Registration #13	2019-03-20	95.377 mi
Registration #14	2019-03-20	95.377 mi
Registration #15	2019-03-20	95.377 mi
Registration #16	2019-03-20	95.377 mi
Registration #17	2019-03-20	95.377 mi
Registration #18	2019-03-20	95.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4807 mm
Wheel base	2857 mm
Kerb weight	2158 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1044305