



report date: 2024-03-29

## General information

Make	VOLVO
Model	V50 E4 D SE V50
Colour	Blue
Year of manufacture	2006
Top speed	130 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-14
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-18
MOT pass rate	83 %
MOT passed	15
Failed MOT tests	3
Total advice items	28
Total items failed	9

MOT #18	2023-05-19 13:32
MOT test number	591924109543
Result	✓ Passed
Next expiry date	2024-05-18
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Power steering component has slight seepage from a component At power steering rack (2.1.5 (a))

MOT #17	2023-05-18 11:46
MOT test number	150407915374
Result	✗ Failed
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Front Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))
Advice	Power steering component has slight seepage from a component At power steering rack (2.1.5 (a))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Fail	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Fail	Offside Front Suspension arm pin or bush excessively worn Rear bush (5.3.4 (a) (i))

**MOT #16** 2022-02-07 10:58**MOT test number** 193005178565**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))**MOT #15** 2021-02-15 16:26**MOT test number** 341535739211**Result** ✓ Passed**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #14** 2021-02-15 11:36**MOT test number** 618425191085**Result** ✗ Failed**Fail** Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**Pass with rectification** Front Registration plate does not conform to the specified requirements (0.1 (d))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Fail** Nearside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #13** 2020-02-18 11:45**MOT test number** 937202095292**Result** ✓ Passed

**MOT #12** 2019-02-14 11:10**MOT test number** 42223586891**Result** ✓ Passed**Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #11** 2018-02-07 12:30**MOT test number** 326693262689**Result** ✓ Passed**MOT #10** 2017-02-22 17:37**MOT test number** 931715642576**Result** ✓ Passed**MOT #9** 2017-02-22 16:51**MOT test number** 147247722055**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #8** 2016-02-16 16:52**MOT test number** 478345972995**Result** ✓ Passed**Advice** Offside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear tyre slightly misshapen**Advice** Nearside Front Inner Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Rear both rear indicators starting to go white

**MOT #7** 2015-02-26 11:44**MOT test number** 258377555014**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Both front tyres wearing on inner edges**MOT #6** 2014-02-14 11:33**MOT test number** 916385344009**Result** ✓ Passed**MOT #5** 2013-02-14 10:25**MOT test number** 729215243076**Result** ✓ Passed**Notice** Exhaust corroded**Notice** Sills covered**Notice** Front discs worn**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Stone chips in windscreen**MOT #4** 2012-02-23 12:49**MOT test number** 107954852083**Result** ✓ Passed**Notice** Front tyres wearing low on inner edges**Notice** Both rear anti roll bar link rod rubbers age cracking**Notice** Unable to check outer sills fully due to sidekirts fitted



MOT #3	2011-03-11 13:34
MOT test number	846850771019
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2	2010-03-17 16:23
MOT test number	613716970071
Result	✓ Passed

MOT #1	2009-03-25 14:25
MOT test number	200084589084
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
18 May 2024

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	18 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>RV06LFH</b>
Plate since	2024-03-29
Current registration	<b>RV06LFH</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2006-03-01
Last registration	2023-05-19
Complete history	<a href="#">See info</a>



Registration #1	2006-03-01	28 mi
Registration #2	2009-03-25	34.967 mi
Registration #3	2010-03-17	42.663 mi
Registration #4	2011-03-11	47.912 mi
Registration #5	2012-02-23	53.283 mi
Registration #6	2013-02-14	58.633 mi
Registration #7	2014-02-14	64.361 mi
Registration #8	2015-02-26	68.268 mi
Registration #9	2016-02-16	70.500 mi
Registration #10	2017-02-22	72.677 mi
Registration #11	2018-05-29	75.277 mi
Registration #12	2019-05-29	78.277 mi
Registration #13	2020-05-29	81.277 mi
Registration #14	2021-05-29	84.277 mi
Registration #15	2022-05-29	87.277 mi
Registration #16	2023-05-29	90.277 mi
Registration #17	2024-05-29	93.277 mi
Registration #18	2025-05-29	96.277 mi
Registration #19	2026-05-29	99.277 mi
Registration #20	2027-05-29	102.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4514 mm
Wheel base	2640 mm
Kerb weight	1489 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4014833