



report date: 2024-03-28

General information

Make	MINI
Model	MINI (R57) COOPER S
Colour	Black
Year of manufacture	2009
Top speed	140 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	172 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 2

Date	2021-09-15
Pictures	13
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](#)

Entry 1

Date	2021-09-14
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2024-10-20
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	15
Total items failed	1

## MOT #15 2023-10-18 15:19

MOT test number 431156965718

Result ✓ Passed

Next expiry date 2024-10-20

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn low smooth on edges 205/45 rf 17 84v (5.2.3 (e))

**Advice** Tyre pressure warning lamp staying lit

**Advice** Oil leak, but not excessive engine dripping on exhaust (8.4.1 (a) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn low smooth on edges (5.2.3 (e))

## MOT #14 2023-10-16 14:15

MOT test number 967189386841

Result ✗ Failed

**Fail** Front Exhaust has a major leak of exhaust gases flexible connector deteriorated blowing at rear (6.1.2 (a))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge worn low smooth on edges (5.2.3 (e))

**Advice** Tyre pressure warning lamp staying lit

**Advice** Oil leak, but not excessive engine dripping on exhaust (8.4.1 (a) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn low smooth on edges 205/45 rf 17 84v (5.2.3 (e))

**MOT #13** 2022-10-18 16:02**MOT test number** 871727584670**Result** ✓ Passed**MOT #12** 2021-10-21 12:56**MOT test number** 119901365085**Result** ✓ Passed**MOT #11** 2021-02-11 10:24**MOT test number** 826039196482**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner and outer edges (5.2.3 (e))**Advice** Front Oil leak, but not excessive very minor oil leak (8.4.1 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge on inner and outer edges (5.2.3 (e))**MOT #10** 2020-02-15 12:10**MOT test number** 935547256738**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2019-02-16 11:06**MOT test number** 957245815651**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



<b>MOT #8</b>	2018-02-28 11:16
<b>MOT test number</b>	311722309666
<b>Result</b>	✓ Passed
<b>MOT #7</b>	2017-10-31 11:30
<b>MOT test number</b>	837772607379
<b>Result</b>	✓ Passed
<b>MOT #6</b>	2017-03-09 09:09
<b>MOT test number</b>	371003490937
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2016-03-24 15:14
<b>MOT test number</b>	621530569290
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2015-03-14 08:42
<b>MOT test number</b>	149763575423
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2014-03-21 12:15
<b>MOT test number</b>	156450884474
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2013-03-25 15:26
<b>MOT test number</b>	146134983089
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2012-03-15 12:02
<b>MOT test number</b>	518335172072
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2024

✓  
**MOT**  
**Expires:**  
20 October 2024

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	2
<b>MOT expiry date</b>	20 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>RO09CDY</b>
Plate since	2019-09-28
Current registration	<b>RO09CDY</b>
Plate since	2019-09-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-03-30
Last registration	2023-10-18
Complete history	<a href="#">See info</a>



Registration #1	2009-03-30	29 mi
Registration #2	2012-03-15	24.883 mi
Registration #3	2013-03-25	30.626 mi
Registration #4	2014-03-21	36.280 mi
Registration #5	2015-03-14	42.917 mi
Registration #6	2016-03-24	49.132 mi
Registration #7	2017-03-09	55.231 mi
Registration #8	2017-10-31	59.404 mi
Registration #9	2018-02-28	59.622 mi
Registration #10	2018-05-01	59.840 mi
Registration #11	2018-07-03	60.058 mi
Registration #12	2018-09-05	60.276 mi
Registration #13	2018-11-07	60.494 mi
Registration #14	2019-01-09	60.712 mi
Registration #15	2019-03-11	60.930 mi
Registration #16	2019-05-13	61.148 mi
Registration #17	2019-07-15	61.366 mi
Registration #18	2023-10-18	61.584 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3714 mm
Wheel base	2467 mm
Kerb weight	1130 kg
Max. allowed weight	1580 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats 4

Number of axles	2
Engine number	A9871363