





General information

Make	RENAULT
Model	ZOE DYNAMIQUE NAV
Colour	Black
Year of manufacture	2015
Top speed	84 mph
0 - 60 mph	13.5 seconds
Gearbox	1 speed automatic

Engine & fuel consumption

Power	91 BHP
Max. torque	220 Nm at 2.500 rpm
Fuel type	Electricity







Internet history

Entry 1

Date


Pictures

2021-02-08

11

Listing price

View report



source: yesauto.com



MOT history

MOT expiry date	2025-02-10
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	14
Total items failed	0

MOT #11	2024-02-07 15:19
MOT test number	220359307832
Result	✓ Passed
Next expiry date	2025-02-10
Advice Vehicles internal headlight adjuster altered to recheck lights	

MOT #10		2024-02-06 10:19
MOT test	number	669212040033
Result		🗙 Failed
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
MAJOR	Offside Stop lamp(s) emits other than a steady red light (4.3.3 (a) (ii))	
Advice	Vehicles internal headlight adjuster altered to recheck lights	

MOT #9		2024-02-06 09:30
MOT test	number	757761033429
Result		🗙 Failed
MAJOR	Offside Stop lamp(s) emits other than a steady red light (4.3.3 (a) (ii))	
Advice	Vehicles internal headlight adjuster altered to recheck lights	





MOT #8		2024-02-05 16:51
MOT test	number	441166355434
Result		🗙 Failed
MAJOR Advice	Offside Stop lamp(s) emits other than a steady red light (4.3.3 (a) (ii)) Vehicles internal headlight adjuster altered to recheck lights	

MOT #7	2023-02-09 15:46
MOT test number	222010010196
Result	✓ Passed

MOT #6	2023-02-08 1	5:33
MOT test	number 450899965	5128
Result	× Fa	ailed
MAJOR Offside Front Lower Suspension arm ball joint excessively worn wishbone (5.3.4 (a) (i))		
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))	
MAJOR Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction parking permit within swept area (3.1 (a) (ii))		

MOT #5	2022-02-11 15:02
MOT test number	697186642838
Result	✓ Passed
Advice Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))	
Advice Front Outer Anti-roll bar ball joint has slight play slight play both sides (5.3.4 (a) (i))	
Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords side wall kerb damage (5.2.3 (d) (i))	

МОТ #4	2021-02-09 16:31
MOT test number	540479608287
Result	✓ Passed





MOT #3	2020-11-04 10:13
MOT test number	614936887558
Result	✓ Passed
MOT #2	2019-05-04 13:58
MOT test number	307280462684
Result	✓ Passed
MOT #1	2018-05-11 11:01
MOT test number	501315030671
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due:	✓ MOT Expires:
1 March 2025 Tax status	10 February 2025 Valid until 1 March
Days left	305
MOT expiry date	10 February 2025
Full MOT history	See MOT history





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

NUMBER OF TAXABLE	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-09-16
Last registration	2024-02-07
Complete history	See info



Registration #1	2015-09-16	23 mi
Registration #2	2018-05-11	14.733 mi
Registration #3	2019-05-04	20.466 mi
Registration #4	2020-11-04	33.253 mi
Registration #5		11.777 mi
Registration #6	2021-02-09	35.190 mi
Registration #7	2022-02-11	38.953 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		10.309 mil





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
50566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	89%
Children	80%
Pedestrian	66%
Safety systems	85%
Overall rating	82%
Video	see crash video



Dimensions & weight	
Width	1730 mm
Height	1562 mm
Length	4084 mm
Wheel base	2588 mm
Kerb weight	1468 kg
Max. allowed weight	1965 kg
Additional information	
Fuel delivery	Not Applicable
	_

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 12/12