



Y629HOD

report date: 2024-03-29

General information

|                     |                        |
|---------------------|------------------------|
| Make                | VOLKSWAGEN             |
| Model               | TRANSPORTER 1.9SDI VAN |
| Colour              | Red                    |
| Year of manufacture | 2001                   |
| Gearbox             | 5 speed Manual         |

Engine & fuel consumption

|                 |          |
|-----------------|----------|
| Engine capacity | 1.896 cc |
| Cylinders       | 4        |
| Fuel type       | Diesel   |



LABEL UNKNOWN



Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-06-06                  |
| Pictures      | 7                           |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-06-06 |
| MOT pass rate      | 61 %       |
| MOT passed         | 17         |
| Failed MOT tests   | 11         |
| Total advice items | 89         |
| Total items failed | 28         |

MOT #282023-06-05 11:28

MOT test number410965884199

Result✓ Passed

Next expiry date2024-06-06

- Minor

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Minor

Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice

Nearside Front sill corroded outside prescribed area
- Minor

Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Brake cable damaged but not to excess (1.1.15 (a))

**MOT #27**

2022-06-07 14:41

**MOT test number**

691925369394

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside sill corroded outside prescribed area
- Advice** Brake cable damaged but not to excess (1.1.15 (a))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #26**

2022-06-06 11:52

**MOT test number**

351753424080

**Result**

✗ Failed

- MAJOR** Rear Seat belt missing (7.1.2 (a))
- Advice** Brake cable damaged but not to excess (1.1.15 (a))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Nearside sill corroded outside prescribed area
- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- MAJOR** Horn not working (7.7 (a))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #25**

2021-05-24 15:10

**MOT test number**

737688229701

**Result**

✓ Passed

**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** N/s sill inner corroded/holed - outside prescribed area**Advice** N/s outer sill slight corrosion**MOT #24**

2021-05-24 07:53

**MOT test number**

766722515858

**Result**

✗ Failed

**MAJOR** Nearside Rear Seat belt buckle missing (7.1.2 (d))**Advice** N/s sill inner corroded/holed - outside prescribed area**MAJOR** Offside Front Suspension component ball joint excessively worn (5.3.4 (a) (i))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Trailer electrical socket likely to become detached (4.10 (a) (ii))**MAJOR** Offside Rear Seat belt buckle missing (7.1.2 (d))**Advice** N/s outer sill slight corrosion**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #23**

2020-07-09 13:19

**MOT test number**

290096614078

**Result**

✓ Passed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Intermittent horn issue
- Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Offside Rear Inner Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #22**

2020-04-27 09:44

**MOT test number**

217003714706

**Result**

✗ Failed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))
- Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- MAJOR** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- MAJOR** Offside Front Service brake excessively fluctuating (1.2.1 (e))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #21** 2018-09-12 09:58**MOT test number** 879756975795**Result** ✓ Passed**MOT #20** 2018-09-11 10:04**MOT test number** 156661776915**Result** ✗ Failed**MAJOR** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #19** 2017-10-10 17:07**MOT test number** 419041107386**Result** ✓ Passed**MOT #18** 2017-09-25 10:20**MOT test number** 482670688050**Result** ✗ Failed**Fail** Offside rear brake binding (3.7.B.1)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Horn not working (1.6.2a)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Fail** Steering system excessively rough (2.2.D.1)**MOT #17** 2016-09-26 10:18**MOT test number** 500782557043**Result** ✓ Passed

**MOT #16**

2016-09-22 15:03

**MOT test number**

736554172015

**Result****✗ Failed****Fail** Fuel system component leaking on engine (7.2.3)**Advice** Rear Tailgate wont stay up unaded.**MOT #15**

2015-10-06 14:51

**MOT test number**

508163861916

**Result****✓ Passed****Advice** Both front tyres going out of shape**Advice** Brake pump/compressor drive belt slightly deteriorated (3.6.F.1)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Offside Front Brake pad shim rubbing on disc**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**MOT #14**

2015-10-06 14:28

**MOT test number**

390275851127

**Result****✗ Failed****Advice** Brake pump/compressor drive belt slightly deteriorated (3.6.F.1)**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Offside Front Brake pad shim rubbing on disc**Fail** Offside Headlamp not working on main beam (1.7.5a)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Both front tyres going out of shape





|  |                  |
|--|------------------|
| <b>MOT #13</b>                                     | 2014-10-01 11:57 |
| <b>MOT test number</b>                             | 316904674266     |
| <b>Result</b>                                      | ✓ Passed         |
| <b>Notice</b> Play in steering rack inner joint(s) |                  |

|   |                  |
|---|------------------|
| <b>MOT #12</b>  | 2014-09-30 10:11 |
| <b>MOT test number</b>  | 938683774278     |
| <b>Result</b>   | ✗ Failed         |
| <b>Notice</b> Play in steering rack inner joint(s)                            |                  |
| <b>Fail</b> Nearside Rear rear brake recording little or no effort (3.7.B.5a) |                  |
| <b>Fail</b> Offside Front Headlamp aim too low (1.8)                          |                  |
| <b>Fail</b> Parking brake: efficiency below requirements (3.7.B.7)            |                  |

|  |                  |
|--|------------------|
| <b>MOT #11</b>   | 2013-09-23 09:24 |
| <b>MOT test number</b>                                     | 239776963251     |
| <b>Result</b>  | ✓ Passed         |
| <b>Advice</b> Tyre worn close to the legal limit (4.1.E.1) |                  |
| <b>Notice</b> Oil leak                                     |                  |
| <b>Advice</b> Brake hose slightly deteriorated (3.6.B.4d)  |                  |
| <b>Notice</b> Play in nsf inner steering rack joint        |                  |

|  |                  |
|--|------------------|
| <b>MOT #10</b>                                     | 2012-10-05 16:16 |
| <b>MOT test number</b>                             | 437499072234     |
| <b>Result</b>                                      | ✓ Passed         |
| <b>Notice</b> 15 inch tyres fitted at time of test |                  |

**MOT #9**

2012-10-04 09:10

**MOT test number**

925728272253

**Result****✗ Failed**

- Fail** Offside Front Headlamp aim too low (1.8)
- Fail** Offside Front Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Nearside Rear Stop lamp not working (1.2.1b)
- Fail** Nearside Front Steering rack gaiter insecure (2.2.D.2d)
- Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Horn not working (1.6.2a)
- Notice** 15 inch tyres fitted at time of test
- Fail** Nearside Front Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)
- Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Front Steering rack gaiter insecure (2.2.D.2d)
- Fail** Offside Rear Stop lamp not working (1.2.1b)
- Fail** Nearside Front Front wheel bearing has excessive play (2.5.A.3c)
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #8**

2011-10-10 13:04

**MOT test number**

655853381264

**Result****✓ Passed**

- Notice** Advise o/s/r tyre worn on inner edge
- Notice** Advise oil light on
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Advise slight play in steering rack

**MOT #7**

2011-10-06 11:20

**MOT test number**

826069271234

**Result****✗ Failed****Notice**

Advise oil light on

**Fail**

Nearside Headlamp aim too low (1.8)

**Fail**

Nearside rear parking brake recording little or no effort (3.7.B.6a)

**Notice**

Advise slight play in steering rack

**Fail**

Nearside Registration plate lamp not working (1.1.C.1d)

**Fail**

Parking brake: efficiency below requirements (3.7.B.7)

**Advice**

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Notice**

Advise o/s/r tyre worn on inner edge

**Fail**

Offside Front position lamp(s) not working (1.1.A.3b)

**MOT #6**

2010-04-21 15:50

**MOT test number**

190561910198

**Result****✓ Passed****Advice**

Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5**

2009-04-04 10:45

**MOT test number**

330394799049

**Result****✓ Passed****MOT #4**

2008-03-05 11:13

**MOT test number**

783905068039

**Result****✓ Passed**



|                 |  |
|-----------------|--|
| MOT #3          | 2007-01-17 16:52                         |
| MOT test number | 213617517065                             |
| Result          | ✓ Passed                                 |
| Notice          | Exhaust heat sheild loose                |
| Notice          | Slight play in steering rack             |
| Advice          | Rear brake disc slightly pitted (3.5.1h) |

|                 |                  |
|-----------------|------------------|
| MOT #2          | 2006-07-21 14:52 |
| MOT test number | 983162206243     |
| Result          | ✓ Passed         |

|                 |   |
|-----------------|---|
| MOT #1          | 2006-07-20 14:51  |
| MOT test number | 783791806238  |
| Result          | ✗ Failed  |
| Fail            | Windscreen washer provides insufficient washer liquid (8.2.3) |
| Fail            | Nearside Registration plate lamp not working (1.1.5c)         |
| Fail            | Brake warning device not working correctly (3.3.D.3a)         |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
6 June 2024

|                  |  |                                 |
|------------------|--|---------------------------------|
| Tax status       |  | Valid until 1 July              |
| Days left        |  | 62                              |
| MOT expiry date  |  | 6 June 2024                     |
| Full MOT history |  | <a href="#">See MOT history</a> |




Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.


Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

|                      |  |
|----------------------|--|
| Number of plates     | 1  |
| Current registration |  <b>Y629HOD</b> |
| Plate since          | 2020-03-29   |
| Current registration |  <b>Y629HOD</b> |
| Plate since          | 2020-03-29   |

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

|                   |            |        |
|-------------------|------------|--------|
| Finance company   | XXXXXXXXXX | XXXXXX |
| Date of agreement | XXXXXXXXXX | XXXXXX |
| Agreement type    | XXXXXXXXXX | XXXXXX |
| Agreement term    | XXXXXXXXXX | XXXXXX |
| Agreement number  | XXXXXXXXXX | XXXXXX |
| Contact info      | XXXXXXXXXX | XXXXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 30                       |
| First mileage registration | 2001-08-01               |
| Last registration          | 2023-06-05               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2001-08-01 | 16 mi      |
| Registration #2  | 2006-07-20 | 137.257 mi |
| Registration #3  | 2006-07-21 | 137.257 mi |
| Registration #4  | 2007-01-17 | 140.552 mi |
| Registration #5  | 2008-03-05 | 147.393 mi |
| Registration #6  | 2009-04-04 | 149.681 mi |
| Registration #7  | 2010-04-21 | 154.327 mi |
| Registration #8  | 2011-10-06 | 154.353 mi |
| Registration #9  | 2011-10-10 | 154.356 mi |
| Registration #10 | 2012-10-04 | 168.971 mi |
| Registration #11 | 2012-10-05 | 168.971 mi |
| Registration #12 | 2013-09-23 | 183.288 mi |
| Registration #13 | 2014-09-30 | 192.631 mi |
| Registration #14 | 2014-10-01 | 192.631 mi |
| Registration #15 | 2015-10-06 | 206.964 mi |
| Registration #16 | 2016-05-20 | 211.277 mi |
| Registration #17 | 2016-05-20 | 211.277 mi |
| Registration #18 | 2016-05-20 | 211.277 mi |
| Registration #19 | 2016-05-20 | 211.277 mi |
| Registration #20 | 2016-05-20 | 211.277 mi |
| Registration #21 | 2016-05-20 | 211.277 mi |
| Registration #22 | 2016-05-20 | 211.277 mi |
| Registration #23 | 2016-05-20 | 211.277 mi |
| Registration #24 | 2016-05-20 | 211.277 mi |
| Registration #25 | 2016-05-20 | 211.277 mi |
| Registration #26 | 2016-05-20 | 211.277 mi |

|                  |            |            |
|------------------|------------|------------|
| Registration #27 | 2025-25-25 | 25,252 442 |
| Registration #28 | 2025-25-25 | 25,252 442 |
| Registration #29 | 2025-25-25 | 25,252 442 |
| Registration #30 | 2025-25-25 | 25,252 442 |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1695 mm |
| Kerb weight         | 1105 kg |
| Max. allowed weight | 1730 kg |

Additional information

|                 |           |
|-----------------|-----------|
| Number of axles | 2         |
| Engine number   | AYQ039579 |