



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D3 R-DESIGN
Colour	White
Year of manufacture	2012
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 1.500 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	55.4 mpg
CO2 emission	134 g/km
CO2 label	E






Internet history

Entry 2

Date	2023-02-20
Pictures	8
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

Entry 1

Date	2022-02-01
Pictures	0
Listing price	<a href="#">View report</a>

source: autotrader.co.uk



## MOT history

MOT expiry date	2025-03-01
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	18
Total items failed	2

MOT #12 2024-03-01 10:46

MOT test number 874913026323

Result ✓ Passed

Next expiry date 2025-03-01

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Side wall cracked (5.2.3 (d) (ii))

**Advice** Suspension arm pin or bush worn but not resulting in excessive movement Offside & near side front lower deteriorated (5.3.4 (a) (i))

MOT #11 2023-03-02 15:34

MOT test number 792015436650

Result ✓ Passed

MOT #10 2022-10-05 08:59

MOT test number 989728402333

Result ✓ Passed

MOT #9 2021-10-13 07:49

MOT test number 745201990872

Result ✓ Passed

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #8** 2020-10-05 10:45**MOT test number** 530053934581**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush (5.3.4 (a) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2019-09-25 09:48**MOT test number** 755462265105**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #6** 2018-10-22 10:55**MOT test number** 204226333331**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement wishbone rear bush (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #5** 2017-10-23 15:24**MOT test number** 499823963829**Result** ✓ Passed

**MOT #4** 2016-07-25 08:20**MOT test number** 188287179827**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2015-08-19 12:41**MOT test number** 101679770512**Result** ✓ Passed**MOT #2** 2015-06-01 13:17**MOT test number** 648532555100**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #1** 2015-06-01 13:17**MOT test number** 909732555162**Result** ✗ Failed**Notice** Under-trays fitted obscuring some underside components**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Notice** Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
1 March 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	1 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-06-26
Last registration	2024-03-01
Complete history	<a href="#">See info</a>



Registration #1	2012-06-26	6 mi
Registration #2	2015-06-01	27.183 mi
Registration #3	2015-08-19	30.285 mi
Registration #4	2016-07-25	33.231 mi
Registration #5	2017-10-23	36.651 mi
Registration #6	2018-10-22	38.842 mi
Registration #7	2019-09-25	41.285 mi
Registration #8	2020-03-01	43.727 mi
Registration #9	2020-03-01	43.727 mi
Registration #10	2020-03-01	43.727 mi
Registration #11	2020-03-01	43.727 mi
Registration #12	2020-03-01	43.727 mi
Registration #13	2020-03-01	43.727 mi
Registration #14	2024-03-01	43.727 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1454 mm
Length	4476 mm
Wheel base	2640 mm
Kerb weight	1520 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	1115610