





report date: 2024-03-28

General information

Make	FORD
Model	C-MAX ZETEC 125
Colour	Blue
Year of manufacture	2008
Top speed	120 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.8 mpg
CO2 emission	169 g/km
CO2 label	Н



CarCheck.co.uk page 1/14



report date: 2024-03-28

Internet history

Entry 2

Date 2022-09-03

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-08-13

Pictures 21

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-28

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2025-02-22
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	24
Total items failed	11

MOT #19		2024-02-23 14:29
MOT test	number	998711639746
Result		✓ Passed
Next expi	ry date	2025-02-22
Advice	Offside Rear Tyre worn close to legal limit/worn on edge ~2mm, worn	on outer edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 205/50 17,	~3mm (5.2.3 (e))

MOT #18	2022-10-20 10:56
MOT test number	878938238165
Result	✓ Passed

Result		▼ 1 d33Cd
MOT #	17	2022-10-17 11:12
MOT te	st number	269929605783
Result		X Failed
Fail ingress	Nearside Front Inner Drive shaft joint constant velocity boot split or insecutor of dirt (6.1.7 (g) (ii))	re, no longer prevents the
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advid	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/14



report date: 2024-03-28

 MOT #16
 2021-10-22 14:00

 MOT test number
 712898238644

 Result
 ✓ Passed

 MOT #15
 2020-09-02 13:00

 MOT test number
 729643420177

 Result
 ✓ Passed

 Advice
 Items removed from driver's view prior to test

MOT test number

Result

Pass with rectification

Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Items removed from driver's view prior to test

Pass with rectification

Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT test number

Result

Advice Child Seat fitted not allowing full inspection of adult belt

Items removed from driver's view prior to test

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT #12 2019-08-16 09:12 706814727907 **MOT** test number Result × Failed Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) **Advice** Child Seat fitted not allowing full inspection of adult belt **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Items removed from driver's view prior to test Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #11

MOT test number

162929383382

Result

Advice Child Seat fitted not allowing full inspection of adult belt

MOT test number
620872214183

Result
Advice Child Seat fitted not allowing full inspection of adult belt

Fail Nearside Rear Tyre has ply or cords exposed outer sidewall damage (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #9
 2017-09-04 10:03

 MOT test number
 113035252002

 Result
 ✓ Passed

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT #8 2016-09-02 09:02

MOT test number 702108534710

Result \(\sqrt{Passed} \)

Advice Child Seat fitted not allowing full inspection of adult belt

MOT #7 2015-09-02 12:19

MOT test number 407685845274

Result \(\sqrt{Passed} \)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #6 2015-08-24 16:28

MOT test number 536746435229

Result X Failed

Fail Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT #5 2014-09-10 12:30

MOT test number 759503554209

Result

Passed

MOT #4 2014-09-02 14:20

MOT test number 889255344204

Result X Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Nearside Power steering component(s) leaking (2.3.3b)

CarCheck.co.uk page 6/14



report date: 2024-03-28

MOT #3		2013-09-06 13:00
MOT test	number	775079943223
Result		✓ Passed
Notice	Steering rack damp n/s	
Notice	Cut in o/s/r tyre no cords exposed	

MOT #2		2012-09-03 16:11
MOT test	number	918177242230
Result		✓ Passed
Notice	Osf tyre slick on the inner edge	
Notice	Child seat in nsr position not allowing full inspection of the belt	
Advice	Power steering component(s) has slight seepage from a seal (2.3.3b)	
Notice	Rear tyres worn lower on the inner edge	

MOT #1	2011-08-25 12:01
MOT test number	879137131200
Result	✓ Passed

CarCheck.co.uk page 7/14



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 8/14



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

EO58PLU

report date: 2024-03-28

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

More info >

CarCheck.co.uk page 11/14



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-10-15
Last registration	2024-02-23
Complete history	See info



Registration #1	2008-10-15	17 mi
Registration #2	2011-08-25	17.920 mi
Registration #3	2012-09-03	24.393 mi
Registration #4	2013-09-06	31.847 mi
Registration #5	2014-09-02	42.862 mi
Registration #6	2014-09-10	42.875 mi
Registration #7	2015-08-24	45.530 mi
Registration #8	2016-09-02	53.873 mi
Registration #9	2017-09-04	62.840 mi
Registration #10	2018-08-31	74.097 mi
Registration #11	2018-08-31	74.097 mi
Registration #12		71.777 es
Registration #13		71.777 es
Registration #14		71.777 es
Registration #15		71.777 es
Registration #16		71.777 es
Registration #17		71.777 es
Registration #18		71.777 es
Registration #19		11.117 es
Registration #20		71.777 es
Registration #21		9.77 66

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2022 mm
Height	1595 mm
Length	4333 mm
Wheel base	2640 mm
Kerb weight	1409 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	53 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles 2
Engine number 7M13062