





report date: 2024-03-29

General information

Make	CITROEN
Model	BERLINGO HDI XTR
Colour	Silver
Year of manufacture	2012
Top speed	107 mph
0 - 60 mph	14.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/11



MOT history

MOT expiry date	2024-12-20
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	16
Total items failed	5

MOT #9	2023-12-18 15:47
MOT test number	372016991105
Result	✓ Passed
Next expiry date	2024-12-20
Advice Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	

MOT #8	2022-12-17 09:56
MOT test number	659607811902
Result	✓ Passed

MOT #7		2021-12-21 12:08
MOT test	number	381936166478
Result		✓ Passed
Advice	Play in steering rack inner joint(s)	
Minor	Offside Front Inner Drive shaft joint constant velocity boot severely deteri	iorated (6.1.7 (g) (i))
Advice Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice	Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))	
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	

CarCheck.co.uk page 2/11



Minor

Advice (a) (i))

PJ61GLZ report date: 2024-03-29

MOT test number

Result

Advice Rear Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice Play in steering rack inner joint(s)

Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Nearside Front Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4

MOT test number

898288041224

Result

Minor

Nearside Front Windscreen damaged but not adversely affecting driver's view corner (3.2 (a) (i))

Advice

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT test number

177352498453

Result

Fail Front Windscreen washer not working (3.5 (a))

Minor Nearside Front Windscreen damaged but not adversely affecting driver's view corner (3.2 (a) (i))

Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 3/11



MOT #3 2018-05-10 10:17

MOT test number 150103660530

Result ✓ Passed

Advice

Nearside Front Seat belt stitching slightly frayed (5.2.2b)

 MOT #2
 2015-02-19 14:34

 MOT test number
 697520455005

MOT #1 2015-02-19 12:39

MOT test number 647180955034

Result X Failed

Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b)

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	20 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info


More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2012-02-27
Last registration	2023-12-18
Complete history	See info



Registration #1	2012-02-27	23 mi
Registration #2	2015-02-19	46.434 mi
Registration #3	2015-02-19	46.434 mi
Registration #4	2018-05-10	52.054 mi
Registration #5	2020-10-06	54.613 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		

More info >

CarCheck.co.uk page 10/11



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1803 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1426 kg
Max. allowed weight	2065 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBEV3012720

CarCheck.co.uk page 11/11