





report date: 2024-03-29

General information

Make	FIAT
Model	PANDA TWINAIR CROSS
Colour	Green
Year of manufacture	2018
Top speed	104 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	145 Nm at 1.900 rpm
Engine capacity	875 cc
Cylinders	2
Fuel type	Petrol
Consumption city	47.9 mpg
Consumption extra urban	65.7 mpg
Consumption combined	57.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/11



SY67WTL

report date: 2024-03-29

Internet history

Entry 2

Date 2021-08-05

Pictures 9

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-08-04
Pictures	9
Listing price	View report









source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2024-08-24
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #5		2023-08-25 13:56
MOT test	number	317074929192
Result		✓ Passed
Next expiry date 2024-08-24		2024-08-24
Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously	y weakened (1.1.14 (a) (ii))

MOT #4		2023-08-24 12:00
MOT test	number	150711218745
Result		× Failed
Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
MAJOR	MAJOR Front Exhaust has a major leak of exhaust gases flexible basket (6.1.2 (a))	
Advice	Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))

CarCheck.co.uk page 3/11



MOT #3 2022-08-22 12:16

MOT test number 399341760303

Advice Offside Rear Outer Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Nearside Front Inner Brake disc worn, pitted or scored, but not seriously weakened face (1.1.14

(a) (ii))

Advice Nearside Rear Outer Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Nearside Rear Inner Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Offside Rear Inner Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

Advice Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened face (1.1.14 (a)

(ii))

MOT #2 2021-08-24 11:40

MOT test number 144917489878

MOT #1 2021-01-27 11:28

MOT test number 887095682849

CarCheck.co.uk page 4/11



Tax & MOT check





Expires: 24 August 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	24 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report I		e?

	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		100
Current registration	UK CONTRACTOR	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-01-24
Last registration	2023-08-25
Complete history	See info



Registration #1	2018-01-24	21 mi
Registration #2	2021-01-27	13.972 mi
Registration #3		91.777 esi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
50482	
S0501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	82%
Children	63%
Pedestrian	49%
Safety systems	43%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1662 mm
Height	1657 mm
Length	3705 mm
Wheel base	2300 mm
Kerb weight	1090 kg
Max. allowed weight	1585 kg

Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles2Engine number0536454