



report date: 2024-03-29

General information

Make	FIAT
Model	500C POP DUALOGIC
Colour	Black
Year of manufacture	2011
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	50.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	113 g/km
CO2 label	C





Internet history

Entry 4

Date 2021-09-21

Pictures 15

Listing price [View report](#)



source: autotrader.co.uk

Entry 3

Date 2021-09-06

Pictures 15

Listing price [View report](#)



source: autotrader.co.uk

Entry 2

Date 2021-08-07

Pictures 15

Listing price [View report](#)



source: autotrader.co.uk

Entry 1

Date 2021-07-25

CarCheck.co.uk

Pictures

12

Listing price

[View report](#)



source: cargurus.co.uk

**MOT history**

MOT expiry date	2025-04-07
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	16
Total items failed	5

MOT #13	2024-04-08 15:36
MOT test number	826364828364
Result	✓ Passed
Next expiry date	2025-04-07
Advice	Os handbrake effort low

MOT #12	2022-09-08 14:45
MOT test number	265691501188
Result	✓ Passed

MOT #11	2021-07-09 08:59
MOT test number	444341910163
Result	✓ Passed

MOT #10	2020-08-18 15:24
MOT test number	397633374520
Result	✓ Passed
Advice	Nearside Front tyre tread is low
Advice	Rear exhaust is in poor condition

**MOT #9** 2019-08-19 14:16**MOT test number** 582508905284**Result** ✓ Passed**MOT #8** 2019-08-19 14:16**MOT test number** 650949067880**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**MOT #7** 2018-08-16 08:17**MOT test number** 762271607781**Result** ✓ Passed**Advice** Nearside Rear Suspension component pin or bush slightly worn shock absorber top bush (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**MOT #6** 2018-08-15 10:36**MOT test number** 504798516205**Result** ✗ Failed**Advice** Nearside Rear Suspension component pin or bush slightly worn shock absorber top bush (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Fail** Offside Rear Shock absorbers likely to become detached top bush (5.3.2 (a) (ii))**MOT #5** 2017-09-15 11:33**MOT test number** 553150453212**Result** ✓ Passed**Advice** Back box badly corroded**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 195 50 15 (4.1.E.1)

**MOT #4** 2016-09-07 12:31**MOT test number** 313767677115**Result** ✓ Passed**Advice** Exhaust back box corroded (outer skin)**MOT #3** 2016-09-07 09:59**MOT test number** 927171350652**Result** ✗ Failed**Fail** Nearside Headlamp aim too high (1.8)**Advice** Exhaust back box corroded (outer skin)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Headlamp aim too high (1.8)**MOT #2** 2015-09-15 16:15**MOT test number** 543048019624**Result** ✓ Passed**Advice** Corrosion to rear exhaust box**Advice** Nearside daytime running light inoperative but position light still working**Advice** Nearside rear tyre wearing low**Advice** Cut to offside front tyre sidewall**MOT #1** 2014-09-16 17:34**MOT test number** 329329454203**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
7 April 2025

Tax status	Valid until 1 September
Days left	124
MOT expiry date	7 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-09-16
Last registration	2024-04-08
Complete history	See info



Registration #1	2011-09-16	8 mi
Registration #2	2014-09-16	26.569 mi
Registration #3	2015-09-15	34.143 mi
Registration #4	2016-09-07	39.697 mi
Registration #5	2016-09-07	39.697 mi
Registration #6	2017-09-15	45.507 mi
Registration #7	2018-08-15	50.206 mi
Registration #8	2018-08-16	50.206 mi
Registration #9	2019-08-19	56.194 mi
Registration #10	2019-08-19	56.194 mi
Registration #11	2019-08-19	56.194 mi
Registration #12	2019-08-19	56.194 mi
Registration #13	2019-08-19	56.194 mi
Registration #14	2019-08-19	56.194 mi
Registration #15	2019-08-19	56.194 mi
Registration #16	2019-08-19	56.194 mi
Registration #17	2019-08-19	56.194 mi
Registration #18	2019-08-19	56.194 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	6491843