



report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO SZ
Colour	Red
Year of manufacture	2013
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-05-22
Pictures	21
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-12-06
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	3
Total items failed	9

MOT #14	2023-11-23 15:24
MOT test number	514488717720
Result	✓ Passed
Next expiry date	2024-12-06

MOT #13	2023-11-23 12:17
MOT test number	591459027646
Result	✗ Failed
<div><div>Fail</div> Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 155/65/14 (5.2.3 (d) (i))</div>	
<div><div>Advice</div> Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))</div>	
<div><div>Fail</div> Horn not working (7.7 (a))</div>	
<div><div>Advice</div> Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))</div>	
<div><div>Advice</div> Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))</div>	

MOT #12	2022-12-01 15:15
MOT test number	613485696101
Result	✓ Passed

**MOT #11** 2022-12-01 14:18**MOT test number** 489577491305**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #10** 2021-11-29 16:39**MOT test number** 530011580292**Result** ✓ Passed**MOT #9** 2020-12-02 13:16**MOT test number** 229652817574**Result** ✓ Passed**MOT #8** 2020-12-02 13:16**MOT test number** 703433052618**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #7** 2019-12-05 12:22**MOT test number** 947523088866**Result** ✓ Passed**MOT #6** 2019-12-05 10:20**MOT test number** 923543768344**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))



MOT #5	2018-11-27 16:35
---------------	------------------

MOT test number	258322645850
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2018-11-27 10:03
---------------	------------------

MOT test number	783487324136
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Nearside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
-------------	--

MOT #3	2017-12-07 14:37
---------------	------------------

MOT test number	599803998853
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2017-02-13 10:48
---------------	------------------

MOT test number	367534455970
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2016-02-08 09:10
---------------	------------------

MOT test number	256070557735
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
6 December 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	6 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	 
Plate since	2019-09-29
Current registration	 
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2013-02-20
Last registration	2023-11-23
Complete history	See info



Registration #1	2013-02-20	8 mi
Registration #2	2016-02-08	10.325 mi
Registration #3	2017-02-13	13.401 mi
Registration #4	2017-12-07	14.083 mi
Registration #5	2018-11-27	22.454 mi
Registration #6	2018-11-27	22.456 mi
Registration #7	2019-12-05	29.175 mi
Registration #8	2019-12-05	29.175 mi
Registration #9	2019-12-05	29.175 mi
Registration #10	2019-12-05	29.175 mi
Registration #11	2019-12-05	29.175 mi
Registration #12	2019-12-05	29.175 mi
Registration #13	2019-12-05	29.175 mi
Registration #14	2019-12-05	29.175 mi
Registration #15	2019-12-05	29.175 mi
Registration #16	2019-12-05	29.175 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Kerb weight	930 kg
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1640153