





report date: 2024-03-28

#### General information

Make	FORD
Model	MONDEO TITANIUM X 130
Colour	Black
Year of manufacture	2008
Top speed	124 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed automatic

### Engine & fuel consumption

Power	130 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	28.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.8 mpg
CO2 emission	189 g/km
CO2 label	J



CarCheck.co.uk page 1/14



report date: 2024-03-28

## Internet history

F	n	t	r۱	,	2
_				,	_

Date	2021-07-25
Pictures	0
Listing price	View report

#### source: autotrader.co.uk

#### Entry 1

Date	2021-06-06
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/14



## **EN08WBE**

report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT overing data	2022 00 12
MOT expiry date	2022-09-12
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	23
Total items failed	17

MOT #17		2021-09-13 15:08
MOT test	number	294008405220
Result		✓ Passed
Next expi	ry date	2022-09-12
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in exc	cessive movement (5.3.4
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #16	2020-09-04 15:22
MOT test number	213874210248
Result	<b>✓</b> Passed
MOT #15	2019-08-22 13:52
MOT test number	993839807198
Result	<b>✓</b> Passed

MOT #14	2018-09-05 16:26
MOT test number	279034016929
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/14



report date: 2024-03-28

**MOT #13** 2018-09-03 14:12

**MOT test number** 752620515205

Result X Failed

Fail Nearside Rear Suspension arm pin or bush excessively worn Trailing arm (5.3.4 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Rear Exhaust heat shield insecure

**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #12** 2017-08-25 15:38

**MOT test number** 828656696015

**Result** ✓ Passed

**MOT #11** 2016-08-25 14:05

**MOT test number** 964456550299

Result \( \sqrt{Passed} \)

Advice Offside Front Tyre worn close to the legal limit bald on inner and outer tread (4.1.E.1)

Advice Child Seat fitted not allowing full inspection of adult belt

**MOT #10** 2015-09-11 08:28

MOT test number 178726450936

Result 

Passed

**Advice** Both rear tyres distorted

CarCheck.co.uk page 4/14



report date: 2024-03-28

MOT test number

Result

Fail Front brake disc in such a condition that it is seriously weakened (3.5.1i)

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)

Advice Both rear tyres distorted

MOT #8

MOT test number

Result

Advice

Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT** #7 2014-07-31 11:32 807792214219 **MOT** test number Result × Failed Fail Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b) **Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Fail Horn not working (1.6.2a) Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b) **Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 5/14



report date: 2024-03-28

MOT test number

Result

Advice

Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice

Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Notice

Nearside front tyre has un-even wear on inside edge

**MOT #5** 2013-08-19 11:48 **MOT** test number 898191333232 Result × Failed **Notice** Offside front tyre perrished Fail Offside Rear Stop lamp not working (1.2.1b) **Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a) **Notice** Nearside front tyre has un-even wear on inside edge **Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #4

MOT test number

S85265902239

Result

Notice Nearside and Offside Front tyres VERY HEAVELY WORN ON INNER EDGES

CarCheck.co.uk page 6/14



Notice

**EN08WBE** 

report date: 2024-03-28

MOT test number

246435202275

Result

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Pass with rectification Offside Front Headlamp aim too high and too far to the right. (1.8)

Fail Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

Nearside and Offside Front tyres VERY HEAVELY WORN ON INNER EDGES

Pass with rectification Nearside Front Headlamp aim too low and too far to the right. (1.8) **MOT #2** 2011-07-29 15:57 **MOT** test number 379340811295 Result ✓ Passed **MOT #1** 2011-07-29 10:02 **MOT** test number 415170911292 Result × Failed Fail Offside Front Tyre has ply or cords exposed (4.1.D.1b) Fail Nearside Front Tyre has ply or cords exposed (4.1.D.1b)

CarCheck.co.uk page 7/14



report date: 2024-03-28

#### Tax & MOT check



**Expired:** 12 September 2022

МОТ

X

Tax expired:
1 April 2022

Tax status

Expired at 1 April 2022

**Days left** 759 days too late

MOT expiry date 12 September 2022

Full MOT history See MOT history

#### Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 8/14




**EN08WBE** 

report date: 2024-03-28

#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



**EN08WBE** 

report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-28

## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report <u>k</u>		ave?
manage of the same		
********		
	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		9
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



report date: 2024-03-28

#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-07-18
Last registration	2021-09-13
Complete history	See info



Registration #1	2008-07-18	10 mi
Registration #2	2011-07-29	86.830 mi
Registration #3	2011-07-29	86.831 mi
Registration #4	2012-07-23	112.252 mi
Registration #5	2012-07-23	112.253 mi
Registration #6	2013-08-19	133.045 mi
Registration #7	2013-08-21	133.072 mi
Registration #8	2014-07-31	154.661 mi
Registration #9	2014-08-01	154.662 mi
Registration #10	2015-09-10	175.035 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.177 ms

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2754 mm
Max. allowed weight	2190 kg

## Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 14/14