



LNI2KXF

report date: 2024-03-29

General information

Make	MINI
Model	MINI (R60) COOPER SD ALL4
Colour	Blue
Year of manufacture	2012
Top speed	120 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	141 BHP
Max. torque	305 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-10-05
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-06-21
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	16
Total items failed	7

MOT #12 2022-06-15 11:08

MOT test number 264757263174

Result ✓ Passed

Next expiry date 2023-06-21

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Hand brake near end of travel

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #11 2021-06-22 13:40

MOT test number 608890777680

Result ✓ Passed

MOT #10 2020-09-28 14:20

MOT test number 344410057774

Result ✓ Passed

Advice Nearside Rear Seat belt buckle slightly damaged buckle surround damaged (7.1.2 (d))

**MOT #9** 2019-09-27 16:11**MOT test number** 752811065595**Result** ✓ Passed**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))**MOT #8** 2019-07-23 12:06**MOT test number** 368461432311**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #7** 2018-04-12 14:42**MOT test number** 816258772451**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #6** 2018-04-12 09:56**MOT test number** 120787288579**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Offside Front wheel bearing rough when rotated (2.5.A.2)

**MOT #5** 2017-04-24 13:57**MOT test number** 467254742113**Result** ✓ Passed**Advice** Both front tyres worn on both edges.**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside rear tyre worn inner edge very low.**MOT #4** 2016-04-28 10:07**MOT test number** 723983694775**Result** ✓ Passed**Advice** Offside rear tyre starting to wear on inner edge.**Advice** Nearside rear brake pads getting low.**MOT #3** 2016-04-28 10:07**MOT test number** 202906452978**Result** ✗ Failed**Advice** Offside rear tyre starting to wear on inner edge.**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside rear brake pads getting low.**MOT #2** 2015-05-11 14:26**MOT test number** 515741135174**Result** ✓ Passed



MOT #1 2015-05-11 10:32

MOT test number 555251835128

Result ✗ Failed

- Fail Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	LN12KXF
Plate since	2019-09-29
Current registration	LN12KXF
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-05-11
Last registration	2022-06-15
Complete history	See info



Registration #1	2012-05-11	18 mi
Registration #2	2015-05-11	32.327 mi
Registration #3	2015-05-11	32.334 mi
Registration #4	2016-04-28	39.275 mi
Registration #5	2016-04-28	39.275 mi
Registration #6	2017-04-24	46.349 mi
Registration #7	2018-04-12	55.670 mi
Registration #8	2019-05-29	65.277 mi
Registration #9	2019-05-29	65.277 mi
Registration #10	2019-05-29	65.277 mi
Registration #11	2019-05-29	65.277 mi
Registration #12	2019-05-29	65.277 mi
Registration #13	2019-05-29	65.277 mi
Registration #14	2019-05-29	65.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Wheel base	2595 mm
Kerb weight	1420 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	72248149