



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	AVENSIS D-4D TR
Colour	Black
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	310 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg



LABEL UNKNOWN

**MOT history**

MOT #14	2021-05-12 17:50
MOT test number	927116913830
Result	✓ Passed
Next expiry date	2022-05-11
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #13	2020-01-10 11:30
MOT test number	978410530218
Result	✓ Passed
Advice	Nearside Non obligatory mirror damaged Side Mirror Glass damaged.
Advice	Rear Both Sides parking brake cable chafed.

MOT #12	2020-01-10 10:52
MOT test number	298681380403
Result	✗ Failed
Fail	Front Tyre tread depth below requirements of 1.6mm Both Sides (5.2.3 (e))
Advice	Rear Both Sides parking brake cable chafed.
Advice	Nearside Non obligatory mirror damaged Side Mirror Glass damaged.

MOT #11	2019-01-28 10:42
MOT test number	686924748493
Result	✓ Passed
Advice	Under tray fitted

**MOT #10** 2019-01-19 13:30**MOT test number** 245386936240**Result** ✗ Failed**Advice** Under tray fitted**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Fail** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #9** 2018-01-19 15:14**MOT test number** 350341421588**Result** ✓ Passed**MOT #8** 2018-01-18 16:45**MOT test number** 901131248753**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Front registration plate deteriorated (6.3.1d)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Nearside Rear Brake pipe excessively corroded (3.6.B.2c)**MOT #7** 2017-01-15 12:27**MOT test number** 629686856958**Result** ✓ Passed**MOT #6** 2016-01-04 13:01**MOT test number** 419609981087**Result** ✓ Passed

**MOT #5** 2014-12-16 12:48**MOT test number** 156820954316**Result** ✓ Passed**MOT #4** 2013-12-16 15:23**MOT test number** 109940553376**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-12-16 13:55**MOT test number** 866770053354**Result** ✗ Failed**Fail** Stop lamp not working (1.2.1b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp aim too low (1.8)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2013-01-07 14:51**MOT test number** 427057503001**Result** ✓ Passed**MOT #1** 2011-12-19 14:44**MOT test number** 897613251396**Result** ✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	ML58YFC
Plate since	2024-03-29
Current registration	ML58YFC
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-01-12
Last registration	2021-05-12
Complete history	See info



Registration #1	2009-01-12	12 mi
Registration #2	2011-12-19	46.448 mi
Registration #3	2013-01-07	62.273 mi
Registration #4	2013-12-16	79.796 mi
Registration #5	2013-12-16	79.796 mi
Registration #6	2014-12-16	94.751 mi
Registration #7	2016-01-04	109.064 mi
Registration #8	2017-01-15	121.313 mi
Registration #9	2019-05-20	151.377 mi
Registration #10	2019-05-20	151.377 mi
Registration #11	2019-05-20	151.377 mi
Registration #12	2019-05-20	151.377 mi
Registration #13	2019-05-20	151.377 mi
Registration #14	2019-05-20	151.377 mi
Registration #15	2019-05-20	151.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1480 mm
Length	4645 mm
Wheel base	2700 mm
Kerb weight	1380 kg
Max. allowed weight	1970 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4415404906