



report date: 2024-03-29

General information

|                     |                    |
|---------------------|--------------------|
| Make                | FORD               |
| Model               | TRANSIT 260 LR P/V |
| Colour              | White              |
| Year of manufacture | 2010               |
| Gearbox             | 5 speed Manual     |

Engine & fuel consumption

|                 |                     |
|-----------------|---------------------|
| Power           | 85 BHP              |
| Max. torque     | 250 Nm at 2.200 rpm |
| Engine capacity | 2.198 cc            |
| Cylinders       | 4                   |
| Fuel type       | Diesel              |



LABEL UNKNOWN



Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-08-27                  |
| Pictures      | 12                          |
| Listing price | <a href="#">View report</a> |



source: cargurus.co.uk



MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-10-04 |
| MOT pass rate      | 65 %       |
| MOT passed         | 11         |
| Failed MOT tests   | 6          |
| Total advice items | 35         |
| Total items failed | 20         |

|         |                  |
|---------|------------------|
| MOT #17 | 2023-10-05 18:05 |
|---------|------------------|

|                 |              |
|-----------------|--------------|
| MOT test number | 768737368771 |
|-----------------|--------------|

|        |          |
|--------|----------|
| Result | ✓ Passed |
|--------|----------|

|                  |            |
|------------------|------------|
| Next expiry date | 2024-10-04 |
|------------------|------------|

- Advice** Nearside Outer Integral body structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Outer Integral body structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))
- Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #16**

2023-10-05 18:05

**MOT test number**

637213098777

**Result**

✗ Failed

**Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Nearside Outer Integral body structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))

**Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**Advice** Offside Outer Integral body structure is corroded but structural rigidity is not significantly reduced sill (6.1.1 (c) (i))

**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #15**

2022-08-12 16:13

**MOT test number**

714988305328

**Result**

✓ Passed

**MOT #14**

2021-08-17 16:03

**MOT test number**

613437896474

**Result**

✓ Passed

**MOT #13**

2021-08-02 13:28

**MOT test number**

669878604282

**Result**

✓ Passed

**Minor** Offside Stop lamp(s) lens defective which has no effect on emitted light (4.3.1 (b) (i))

**MOT #12** 2021-08-02 13:28**MOT test number** 492422014143**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Minor** Offside Stop lamp(s) lens defective which has no effect on emitted light (4.3.1 (b) (i))**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #11** 2019-07-29 14:49**MOT test number** 702514592522**Result** ✓ Passed**Advice** Corroded sump**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #10** 2019-07-29 10:16**MOT test number** 348342566384**Result** ✗ Failed**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Nearside Integral body structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired On the seal (6.2.2 (d) (ii))**Fail** Offside Integral body structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired On the seal (6.2.2 (d) (ii))**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Corroded sump**Fail** Nearside Integral body structure or chassis has excessive corrosion to the extent that overall security or stability of the body is impaired On the seal (6.2.2 (d) (ii))

**MOT #9** 2018-05-15 08:22**MOT test number** 133994555183**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit inner and outer edge (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' X2 small chips, central and ns of screen (8.3.1d)**Advice** Oil leak engine**MOT #8** 2018-05-15 08:22**MOT test number** 217039086349**Result** ✗ Failed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' X2 small chips, central and ns of screen (8.3.1d)**Advice** Oil leak engine**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit inner and outer edge (4.1.E.1)**MOT #7** 2017-06-02 13:06**MOT test number** 580960489380**Result** ✓ Passed**Advice** Engine idle speed uneven**MOT #6** 2017-05-31 09:08**MOT test number** 779200809183**Result** ✗ Failed**Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Engine idle speed uneven**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Nearside Front Nail in tyre

**MOT #5** 2016-03-30 13:36**MOT test number** 413223044120**Result** ✓ Passed**MOT #4** 2016-03-29 10:10**MOT test number** 656990242584**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Centre Stop lamp not working (1.2.1b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**MOT #3** 2015-04-21 10:52**MOT test number** 228361215411**Result** ✓ Passed**Notice** Engine moutains worn



MOT #2

2014-05-02 08:59

MOT test number

349122024188

Result

✓ Passed

- Advice

Offside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice

Front Brake pad(s) wearing thin (3.5.1g)
- Advice

Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice

Offside Front Brake pad(s) wearing thin (3.5.1g)

MOT #1

2013-06-21 13:52

MOT test number

125762173134

Result

✓ Passed

- Advice

Nearside Rear Brake pad(s) wearing thin (3.5.1g)
- Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice

Offside Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
4 October 2024

|                   |                       |
|-------------------|-----------------------|
| <b>Tax status</b> | Valid until 1 October |
|-------------------|-----------------------|

|                  |     |
|------------------|-----|
| <b>Days left</b> | 156 |
|------------------|-----|

|                        |                |
|------------------------|----------------|
| <b>MOT expiry date</b> | 4 October 2024 |
|------------------------|----------------|

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |
|-------------------------|---------------------------------|




Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 10,000 |
| Auction value               | £ 10,000 |
| Average private trade value | £ 10,000 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this FORD had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration | *****      |
| Plate since          | 2019-03-29 |
| Current registration | *****      |
| Plate since          | 2019-03-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 19                       |
| First mileage registration | 2010-06-30               |
| Last registration          | 2023-10-05               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2010-06-30 | 13 mi      |
| Registration #2  | 2013-06-21 | 39.459 mi  |
| Registration #3  | 2014-05-02 | 46.362 mi  |
| Registration #4  | 2015-04-21 | 88.866 mi  |
| Registration #5  | 2016-03-29 | 120.415 mi |
| Registration #6  | 2016-03-30 | 120.416 mi |
| Registration #7  | 2017-05-31 | 132.715 mi |
| Registration #8  | 2017-06-02 | 132.715 mi |
| Registration #9  | 2018-05-15 | 136.324 mi |
| Registration #10 | 2018-05-15 | 136.324 mi |
| Registration #11 | 2019-05-20 | 151.277 mi |
| Registration #12 | 2019-05-20 | 151.277 mi |
| Registration #13 | 2019-05-20 | 151.277 mi |
| Registration #14 | 2019-05-20 | 151.277 mi |
| Registration #15 | 2019-05-20 | 151.277 mi |
| Registration #16 | 2019-05-20 | 151.277 mi |
| Registration #17 | 2019-05-20 | 151.277 mi |
| Registration #18 | 2019-05-20 | 151.277 mi |
| Registration #19 | 2019-05-20 | 151.277 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1974 mm |
| Height              | 1989 mm |
| Length              | 4863 mm |
| Wheel base          | 3300 mm |
| Kerb weight         | 1699 kg |
| Max. allowed weight | 2600 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 80 l             |
| Fuel delivery      | Direct Injection |
| Number of seats    | 3                |
| Number of axles    | 2                |
| Engine number      | AU65513          |