



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D2 ES
Colour	Grey
Year of manufacture	2013
Top speed	121 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption



Power	115 BHP
Max. torque	270 Nm at 2.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1	
Date	2021-08-03
Pictures	38
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-09-24
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	8
Total items failed	1

MOT #12	2023-09-25 12:51
MOT test number	698058305916
Result	✓ Passed
Next expiry date	2024-09-24

MOT #11	2023-09-25 10:08
MOT test number	491443014754
Result	✗ Failed
<b>MAJOR</b> Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords inner edge (5.2.3 (d) (i))	
<b>Advice</b> Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #10	2022-09-13 14:59
MOT test number	897580345179
Result	✓ Passed

MOT #9	2022-09-13 08:51
MOT test number	359121731484
Result	✗ Failed
<b>DANGEROUS</b> Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
<b>Advice</b> Wheel alignment	



MOT #8	2021-09-23 10:47
--------	------------------

MOT test number	697532842284
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #7	2021-03-04 13:31
--------	------------------

MOT test number	596959973983
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #6	2020-03-07 11:34
--------	------------------

MOT test number	325094055269
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #5	2019-03-08 16:11
--------	------------------

MOT test number	100630993940
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #4	2019-03-08 16:11
--------	------------------

MOT test number	133212145158
-----------------	--------------

Result	✗ Failed
--------	----------

Pass with rectification	Offside Front Position lamp not working (4.2.1 (a))
-------------------------	---

MOT #3	2018-04-14 11:46
--------	------------------

MOT test number	256152423576
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #2	2017-04-15 10:10
--------	------------------

MOT test number	109485716306
-----------------	--------------

Result	✓ Passed
--------	----------



MOT #12016-04-12 10:46

MOT test number200615097620

Result		✓ Passed
Advice	Nearside Front Lower Suspension arm synthetic bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 June 2024

✓  
**MOT**

**Expires:**  
24 September 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	24 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>SV13ZHY</b>
Plate since	2024-03-29
Current registration	<b>SV13ZHY</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-04-30
Last registration	2023-09-25
Complete history	<a href="#">See info</a>



Registration #1	2013-04-30	9 mi
Registration #2	2016-04-12	27.975 mi
Registration #3	2017-04-15	41.551 mi
Registration #4	2018-04-14	49.636 mi
Registration #5	2019-03-08	56.059 mi
Registration #6	2019-03-08	56.059 mi
Registration #7	2020-03-07	68.405 mi
Registration #8	2020-03-07	75.277 mi
Registration #9	2020-03-07	75.277 mi
Registration #10	2020-03-07	75.277 mi
Registration #11	2020-03-07	75.277 mi
Registration #12	2020-03-07	75.277 mi
Registration #13	2020-03-07	75.277 mi
Registration #14	2020-03-07	75.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1519 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	67 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

**Engine number**

2276903