





report date: 2024-03-29

General information

Make	FORD
Model	C-MAX ZETEC
Colour	White
Year of manufacture	2013
Top speed	112 mph
0 - 100 km/h	11.5 seconds
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 kW / 125 HP / 104 BHP	
Max. torque	159 Nm at 4.000 rpm	
Engine capacity	1.596 cc	
Cylinders	4	
Fuel type	Petrol	
Consumption city	33.6 mpg	
Consumption extra urban	54.3 mpg	
Consumption combined	44.1 mpg	
CO2 emission	149 g/km	
CO2 label	F	



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-11-27

Pictures 15

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-12-23
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	9
Total items failed	7

MOT #11	2023-12-15 13:59
MOT test number	166030032607
Result	✓ Passed
Next expiry date	2024-12-23

MOT #10		2022-12-16 10:42
MOT test	number	631776072018
Result		✓ Passed
Advice	Offside Rear Nail in tyre screw in tyre on outer edge of tread no puncture	e repair possible
Advice Offside Rear Outer Child Seat fitted not allowing full inspection of adult belt seat belt not checked		elt seat belt not checked
during inspection		
Advice	Front clutch pedal rubber missing	

MOT #9	2021-12-01 16:32
MOT test number	440885302811
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #8 2021-12-01 11:07

MOT test number 628274870815

Result X Failed

Fail Offside Front Service brake lagging in operation (1.2.1 (d))

Fail Offside Front Service brake excessively binding (1.2.1 (f))

Fail Offside Front Brake pad(s) contaminated (1.1.13 (b))

MOT #7 2020-12-04 16:51

MOT test number 141320027509

Result ✓ Passed

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #6 2020-12-04 11:55

MOT test number 130804501404

Result × Failed

Fail Horn not working (7.7 (a) (ii))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Pass with rectification Windscreen washer not working (3.5 (a))

MOT #5 2019-06-24 14:31

MOT test number 123701010540

Result
✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge on wear limits (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge on wear limits (5.2.3 (e))

CarCheck.co.uk page 4/12



MOT #4

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2017-06-23 11:25 383709535287 **MOT test number** Result ✓ Passed **MOT #2** 2016-06-21 08:58 **MOT** test number 829237572663 Result ✓ Passed MOT #1 2016-06-20 14:49 512228683674 **MOT test number** Result × Failed

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	23 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Venicle class	40
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when motory		
For how long did the current and previous owner(s) have this FORD? How many owners defined the premium report and see all owner registrations. Download the full report by		ave?
THE PARTY OF THE P		

	More info	>
Plate changes		
See in this check if this FORD had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-05-08
Last registration	2023-12-15
Complete history	See info



Registration #1	2013-05-08	15 mi
Registration #2	2016-06-20	34.023 mi
Registration #3	2016-06-21	34.023 mi
Registration #4	2017-06-23	46.560 mi
Registration #5	2018-06-20	57.423 mi
Registration #6	2019-06-24	68.793 mi
Registration #7	2020-12-04	79.212 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		70,777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	92%
Children	83%
Pedestrian	50%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	2067 mm
Height	1626 mm
Length	4380 mm
Wheel base	2850 mm
Kerb weight	1274 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles CarCheck.co.uk	2 page 12/12