



report date: 2024-03-28

General information

Make	FIAT
Model	BRAVO DYNAMIC
Colour	Black
Year of manufacture	2008
Top speed	111 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	128 Nm at 4.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg
CO2 emission	156 g/km
CO2 label	G





MOT history

MOT expiry date	2025-01-24
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	12
Total items failed	20

MOT #21	2024-01-10 12:30
MOT test number	210330535974
Result	✓ Passed
Next expiry date	2025-01-24
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #20	2024-01-09 12:42
MOT test number	936886451905
Result	✗ Failed
Fail	Nearside Front Outer Drive shaft joint constant velocity boot missing (6.1.7 (g) (ii))
Fail	Offside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Fail	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #19	2023-01-25 14:25
MOT test number	387355391022
Result	✓ Passed

**MOT #18**

2023-01-19 15:06

MOT test number

632231409707

Result**✗ Failed****Fail**

Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail

Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail

Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Fail

Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail

Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

MOT #17

2022-01-22 11:29

MOT test number

996084811024

Result**✓ Passed****Advice**

Rear Brake pad(s) wearing thin n/s and o/s (1.1.13 (a) (ii))

Minor

Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice

Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice

Brake disc worn, pitted or scored, but not seriously weakened all four (1.1.14 (a) (ii))

Minor

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

MOT #16

2020-07-13 10:29

MOT test number

406885944387

Result**✓ Passed****MOT #15**

2019-07-26 15:31

MOT test number

560622853399

Result**✓ Passed**

**MOT #14** 2019-07-26 15:31**MOT test number** 813711814992**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #13** 2018-07-30 09:01**MOT test number** 316767920829**Result** ✓ Passed**MOT #12** 2018-07-30 09:01**MOT test number** 749083616895**Result** ✗ Failed**Pass with rectification** Windscreen washer not working (3.5 (a))**MOT #11** 2017-07-28 13:38**MOT test number** 506429487065**Result** ✓ Passed**MOT #10** 2017-07-28 09:17**MOT test number** 684371271320**Result** ✗ Failed**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure in the tread (4.1.D.1b)**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #9** 2016-07-27 14:00**MOT test number** 917938342824**Result** ✓ Passed

**MOT #8** 2016-07-27 11:20**MOT test number** 752719798348**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Nearside Front steering slight play**Fail** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Rear Exhaust system not adequately supported insecure to middle joint (7.1.1)**MOT #7** 2015-07-29 15:15**MOT test number** 938160315224**Result** ✓ Passed**Notice** O/s/r tyre on legal limit 1.6mm**MOT #6** 2015-07-29 10:18**MOT test number** 496060115240**Result** ✗ Failed**Notice** O/s/f tyre on legal limit 1.6mm ADVISE REPLACEMENT**Fail** Nearside Front coil spring broken (2.4.C.1a)**MOT #5** 2014-07-14 10:04**MOT test number** 809265394127**Result** ✓ Passed**MOT #4** 2013-07-09 15:34**MOT test number** 107640593100**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2013-07-08 11:21
MOT test number	608479083144
Result	✗ Failed
Fail	Nearside Front coil spring broken (2.4.C.1a)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2	2012-07-23 14:56
MOT test number	709025102286
Result	✓ Passed

MOT #1	2011-07-26 11:54
MOT test number	169097501253
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
24 January 2025

Tax status	Valid until 1 May
Days left	366
MOT expiry date	24 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	FT08EAE
Plate since	2024-03-28
Current registration	FT08EAE
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-08-02
Last registration	2024-01-10
Complete history	See info



Registration #1	2008-08-02	28 mi
Registration #2	2011-07-26	25.218 mi
Registration #3	2012-07-23	33.593 mi
Registration #4	2013-07-08	40.239 mi
Registration #5	2013-07-09	40.240 mi
Registration #6	2014-07-14	47.622 mi
Registration #7	2015-07-29	54.713 mi
Registration #8	2015-07-29	54.714 mi
Registration #9	2016-07-27	61.827 mi
Registration #10	2016-07-27	61.833 mi
Registration #11	2017-07-28	70.014 mi
Registration #12	2018-07-29	78.195 mi
Registration #13	2019-07-30	86.376 mi
Registration #14	2020-07-31	94.557 mi
Registration #15	2021-08-01	102.738 mi
Registration #16	2022-08-02	110.919 mi
Registration #17	2023-08-03	119.100 mi
Registration #18	2024-01-10	127.281 mi
Registration #19		
Registration #20		
Registration #21		
Registration #22		

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1792 mm
Height	1498 mm
Length	4336 mm
Wheel base	2600 mm
Kerb weight	1205 kg
Max. allowed weight	1715 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1267536