



report date: 2024-03-28

General information

Make	NISSAN
Model	NOTE ACENTA
Colour	Red
Year of manufacture	2012
Top speed	103 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	87 BHP
Max. torque	128 Nm at 3.200 rpm
Engine capacity	1.386 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.7 mpg
Consumption extra urban	55.7 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-02-03
Pictures	9
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-03-09
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	19
Total items failed	15

MOT #16 2024-03-06 17:01

MOT test number 437759387320

Result ✓ Passed

Next expiry date 2025-03-09

Advice Offside Front Suspension component mounting prescribed area is corroded but not considered excessive inner wheel arch (5.3.6 (a) (i))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #15 2023-03-10 16:59

MOT test number 300841392567

Result ✓ Passed

Advice Offside Front Suspension component mounting prescribed area is corroded but not considered excessive inner wing near top shocker mount (5.3.6 (a) (i))

MOT #14 2023-03-08 10:41

MOT test number 565797173307

Result ✗ Failed

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Front Suspension component mounting prescribed area is corroded but not considered excessive inner wing near top shocker mount (5.3.6 (a) (i))

Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #13** 2022-02-24 15:58**MOT test number** 607698184500**Result** ✓ Passed**Advice** Hand brake lever has long travel**Advice** Items removed from driver's view prior to test**Advice** Offside Front Inner Suspension component mounting prescribed area is corroded but not considered excessive wheel arch (5.3.6 (a) (i))**MOT #12** 2022-02-24 15:15**MOT test number** 535790958063**Result** ✗ Failed**Advice** Hand brake lever has long travel**Advice** Items removed from driver's view prior to test**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Inner Suspension component mounting prescribed area is corroded but not considered excessive wheel arch (5.3.6 (a) (i))**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**MOT #11** 2021-03-09 14:12**MOT test number** 862297405218**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge 185-55-16v (5.2.3 (e))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #10** 2021-03-03 12:27**MOT test number** 165250030594**Result** ✗ Failed**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Sub-frame pin or bush excessively worn both rear bushes in front subframe (5.3.4 (a) (i))**Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 185-55-16v (5.2.3 (d) (i))**Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #9** 2020-06-08 12:20**MOT test number** 445065172895**Result** ✓ Passed**MOT #8** 2020-06-08 12:20**MOT test number** 601301722983**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #7** 2019-02-25 09:04**MOT test number** 551435264223**Result** ✓ Passed

**MOT #6** 2019-02-25 09:03**MOT test number** 253666940502**Result** ✗ Failed**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #5** 2018-05-22 12:00**MOT test number** 626437471455**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2018-05-15 09:16**MOT test number** 329977578005**Result** ✗ Failed**Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Fail** Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2017-05-16 09:04**MOT test number** 298515120452**Result** ✓ Passed**MOT #2** 2016-05-20 07:03**MOT test number** 901210690350**Result** ✓ Passed



MOT #1	2015-06-17 13:18
MOT test number	227658865179
Result	✓ Passed
<div>Advice</div> (2.4.G.2)	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
9 March 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	9 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-




Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-06-21
Last registration	2024-03-06
Complete history	See info



Registration #1	2012-06-21	26 mi
Registration #2	2015-06-17	45.943 mi
Registration #3	2016-05-20	49.958 mi
Registration #4	2017-05-16	76.806 mi
Registration #5	2018-05-15	66.464 mi
Registration #6	2018-05-22	66.524 mi
Registration #7	2019-02-25	73.557 mi
Registration #8	2019-02-25	73.557 mi
Registration #9	2020-06-08	88.959 mi
Registration #10	2020-06-08	88.959 mi
Registration #11	2020-06-08	88.959 mi
Registration #12	2020-06-08	88.959 mi
Registration #13	2020-06-08	88.959 mi
Registration #14	2020-06-08	88.959 mi
Registration #15	2020-06-08	88.959 mi
Registration #16	2020-06-08	88.959 mi
Registration #17	2020-06-08	88.959 mi
Registration #18	2020-06-08	88.959 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1691 mm
Height	1550 mm
Length	4083 mm
Wheel base	2600 mm
Kerb weight	1092 kg
Max. allowed weight	1546 kg

Additional information

Fuel tank capacity	46 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	326060
---------------	--------