




report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA SRI NAV 16V
Colour	Black
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg
CO2 emission	175 g/km
CO2 label	H





MOT history

MOT expiry date	2021-01-05
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	18
Total items failed	12

MOT #15	2019-07-05 16:42
MOT test number	249642219784
Result	✓ Passed
Next expiry date	2021-01-05

MOT #14	2018-07-06 08:40
MOT test number	293086290892
Result	✓ Passed

MOT #13	2018-05-30 13:13
MOT test number	629194215768
Result	✓ Passed

**MOT #12**

2018-05-29 09:53

MOT test number

284884316408

Result**✗ Failed**

- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Nearside Front Lower Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #11

2017-05-27 08:53

MOT test number

550117570094

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #10

2016-05-28 09:30

MOT test number

552811955821

Result**✓ Passed**

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Rear s/belt not checked as child seat present
- Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #9** 2016-05-18 09:10**MOT test number** 165517034426**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Rear s/belt not checked as child seat present**MOT #8** 2015-05-30 12:04**MOT test number** 818540155182**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #7** 2015-05-22 13:37**MOT test number** 349622445117**Result** ✗ Failed**Fail** Offside Rear coil spring broken (2.4.C.1a)**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #6** 2014-05-23 13:42**MOT test number** 555303444100**Result** ✓ Passed

**MOT #5** 2014-05-23 13:42**MOT test number** 776513544176**Result** ✗ Failed

- Pass with rectification** Nearside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)
- Pass with rectification** Offside Stop lamp not working (1.2.1b)
- Pass with rectification** Offside Headlamp excessively deteriorated so that the light output is severely reduced (1.7.5a)

MOT #4 2013-07-12 09:21**MOT test number** 356783393122**Result** ✓ Passed

- Advice** Tyre worn close to the legal limit (4.1.E.1)

MOT #3 2012-07-31 15:53**MOT test number** 398493112271**Result** ✓ Passed**MOT #2** 2012-02-21 09:55**MOT test number** 289102752028**Result** ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt
- Notice** Rear tyres slightly out of shape
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Notice** Oil leak



MOT #1	2011-02-24 11:11
MOT test number	758305551012
Result	✓ Passed
Notice	Oil leak
Notice	Child seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Direction indicators slightly discoloured (1.4.A.2f)



Tax & MOT check

✕
Untaxed

Tax expired:
26 January 2021

✕
MOT

Expired:
5 January 2021

Tax status	Expired at 26 January 2021
Days left	1189 days too late
MOT expiry date	5 January 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-03-01
Last registration	2019-07-05
Complete history	See info



Registration #1	2008-03-01	21 mi
Registration #2	2011-02-24	35.892 mi
Registration #3	2012-02-21	44.206 mi
Registration #4	2012-07-31	47.927 mi
Registration #5	2013-07-12	63.478 mi
Registration #6	2014-05-23	69.586 mi
Registration #7	2015-05-22	78.626 mi
Registration #8	2015-05-30	78.768 mi
Registration #9	2016-05-29	88.277 mi
Registration #10	2017-05-29	98.277 mi
Registration #11	2018-05-29	108.277 mi
Registration #12	2019-05-29	118.277 mi
Registration #13	2020-05-29	128.277 mi
Registration #14	2021-05-29	138.277 mi
Registration #15	2022-05-29	148.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4611 mm
Wheel base	2700 mm
Kerb weight	1346 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20LZ4558