



General information

Make	MINI
Model	ROADSTER COOPER
Colour	Black
Year of manufacture	2013
Top speed	124 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E








Internet history

Entry 1

Date	2021-09-26
Pictures	15
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2025-02-01
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	18
Total items failed	2

MOT #12 2024-02-02 09:19**MOT test number** 519484283477**Result** Passed**Next expiry date** 2025-02-01**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #11** 2023-02-01 16:03**MOT test number** 390907203261**Result** Passed**Minor** Nearside Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Minor** Nearside Front Position lamp has a product on the lens or light source which obviously reduces light intensity (4.2.3 (b) (i))

**MOT #10** 2023-02-01 12:25**MOT test number** 895582488210**Result** ✗ Failed**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Minor** Nearside Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Minor** Nearside Front Position lamp has a product on the lens or light source which obviously reduces light intensity (4.2.3 (b) (i))**MOT #9** 2022-01-13 14:43**MOT test number** 369737572542**Result** ✓ Passed**MOT #8** 2021-01-26 15:42**MOT test number** 635050471762**Result** ✓ Passed**MOT #7** 2020-01-30 10:03**MOT test number** 587813175209**Result** ✓ Passed**Advice** Nearside Front Tyre slightly damaged/cracking or perishing wear to outer edge (5.2.3 (d) (ii))**Advice** Engine covers fitted obscuring parts of the test**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing outer edge is nearly smooth (5.2.3 (d) (ii))

**MOT #6** 2020-01-29 14:14**MOT test number** 249108672737**Result** ✗ Failed**MAJOR** Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing wear to outer edge (5.2.3 (d) (ii))**Pass with rectification** Registration plate lamp inoperative in the case of a single lamp or all lamps both (4.7.1 (b) (ii))**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing outer edge is nearly smooth (5.2.3 (d) (ii))**Advice** Engine covers fitted obscuring parts of the test**MOT #5** 2019-01-26 12:24**MOT test number** 893254891382**Result** ✓ Passed**MOT #4** 2018-01-31 13:43**MOT test number** 538274829912**Result** ✓ Passed**MOT #3** 2017-02-02 16:45**MOT test number** 209716330610**Result** ✓ Passed**MOT #2** 2017-02-02 15:45**MOT test number** 668728142491**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)



MOT #1	2008-01-31 13:40
MOT test number	435879768890
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
1 February 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	1 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	WM13AET
Plate since	2015-05-29
Current registration	WM13AET
Plate since	2015-05-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2008-01-31
Last registration	2024-02-02
Complete history	See info



Registration #1	2008-01-31	35.197 mi
Registration #2	2017-02-02	33.325 mi
Registration #3	2017-02-02	33.327 mi
Registration #4	2018-01-31	35.197 mi
Registration #5	2019-01-26	40.824 mi
Registration #6	2020-01-29	44.359 mi
Registration #7	2020-01-30	44.360 mi
Registration #8	2020-01-30	44.360 mi
Registration #9	2020-01-30	44.360 mi
Registration #10	2020-01-30	44.360 mi
Registration #11	2020-01-30	44.360 mi
Registration #12	2020-01-30	44.360 mi
Registration #13	2020-01-30	44.360 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1892 mm
Height	1384 mm
Length	3728 mm
Wheel base	2467 mm
Kerb weight	1120 kg
Max. allowed weight	1410 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2

Engine number	A437J422
---------------	----------