



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Black
Year of manufacture	-
Top speed	107 mph
0 - 60 mph	13.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	48.7 mpg
Consumption combined	37.7 mpg





Internet history

Entry 1

Date	2021-06-23
Pictures	12
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #12	2022-02-04 13:28
MOT test number	933019570065
Result	✓ Passed
Next expiry date	2023-02-04

MOT #11	2021-02-03 13:43
MOT test number	211535037861
Result	✓ Passed
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10	2020-02-05 13:43
MOT test number	122364220442
Result	✓ Passed
Advice	Nearside Front Valve stem slightly damaged Rubber valve stem cracked (5.2.3 (j))
Advice	Nearside Rear Valve stem slightly damaged Rubber valve stem cracked (5.2.3 (j))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Offside front wishbone rear bush deteriorating (5.3.4 (a) (i))
Advice	Offside Front Valve stem slightly damaged Rubber valve stem cracked (5.2.3 (j))

MOT #9	2019-01-16 10:36
MOT test number	260542515422
Result	✓ Passed
Advice	Offside Front Valve stem slightly damaged rubber cracking (5.2.3 (j))
Advice	Nearside Front Valve stem slightly damaged rubber cracking (5.2.3 (j))
Advice	Nearside Rear Valve stem slightly damaged rubber cracking (5.2.3 (j))

**MOT #8** 2018-01-17 09:50**MOT test number** 839689272806**Result** ✓ Passed

Advice Offside Front Tyre worn close to the legal limit tyre on limit/ smooth on inner shoulder recommend early replacement (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit approx 3mm tyre - smooth on inner shoulder (4.1.E.1)

Advice Both rear tyres cracked/ perished

MOT #7 2017-01-17 09:45**MOT test number** 346837003354**Result** ✓ Passed**MOT #6** 2016-01-25 11:09**MOT test number** 927589961194**Result** ✓ Passed**MOT #5** 2016-01-25 11:09**MOT test number** 286604357489**Result** ✗ Failed

Pass with rectification Offside Rear Rear position lamp(s) incorrect colour (1.1.A.3e)

MOT #4 2015-01-23 10:08**MOT test number** 696413325001**Result** ✓ Passed**MOT #3** 2014-02-03 12:52**MOT test number** 377084134010**Result** ✓ Passed



MOT #2	2013-05-20 12:01
MOT test number	768260143135
Result	✓ Passed
<div>NoticeUnder-trays fitted obscuring some underside components</div>	

MOT #1	2013-05-20 12:01
MOT test number	485500943165
Result	✗ Failed
<div>Pass with rectificationOffside Side repeater not working (1.4.A.2c)</div> <div>NoticeUnder-trays fitted obscuring some underside components</div>	



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-06-25
Last registration	2022-02-04
Complete history	See info



Registration #1	2010-06-25	18 mi
Registration #2	2013-05-20	20.608 mi
Registration #3	2014-02-03	23.126 mi
Registration #4	2015-01-23	30.044 mi
Registration #5	2016-01-25	34.395 mi
Registration #6	2016-01-25	34.395 mi
Registration #7	2017-01-17	40.266 mi
Registration #8	2019-05-20	55.277 mi
Registration #9	2019-05-20	55.277 mi
Registration #10	2019-05-20	55.277 mi
Registration #11	2019-05-20	55.277 mi
Registration #12	2019-05-20	55.277 mi
Registration #13	2019-05-20	55.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1314 kg
Max. allowed weight	1835 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AY19587