





report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Grey
Year of manufacture	-
Top speed	96 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Max. torque	102 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg



CarCheck.co.uk page 1/10



report date: 2024-03-29

Passed

MOT history

Result

Advice

 MOT #14
 2021-01-20 14:34

 MOT test number
 358677836698

Result ✓ Passed

Next expiry date 2022-02-13

Advice Gearbox mounting defective

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Brake hose slightly deteriorated both fronts (1.1.12 (b) (ii))

Advice Tyre worn close to legal limit/worn on edge both fronts (5.2.3 (e))

Advice Brake hose slightly deteriorated both rears (1.1.12 (b) (ii))

Minor Offside Front Anti-roll bar ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #13 2020-02-14 10:28

MOT test number 765189832511

Tyre worn close to legal limit/worn on edge both fronts (5.2.3 (e))

MOT #12 2019-01-08 14:33

MOT test number 837343737706

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11 2017-06-28 14:59

MOT test number 801970089749

Result

Passed

Advice Rear exhaust back box corroding.

CarCheck.co.uk page 2/10



report date: 2024-03-29

MOT #10 2017-06-28 13:49

MOT test number 671240095161

Result X Failed

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

Advice Rear exhaust back box corroding.

Fail Offside Registration plate lamp not working (1.1.C.1d)

MOT #9 2016-06-20 08:47

MOT test number 301288959054

Result ✓ Passed

Advice Rear exhaust box outer casing corroded

Advice Coil spring corroded both front (2.4.C.1b)

Advice Coil spring corroded both rear (2.4.C.1b)

MOT #8 2015-06-02 10:43

MOT test number 969393555187

Result ✓ Passed

MOT #7 2014-06-21 12:23

MOT test number 239252274413

Result ✓ Passed

MOT #6 2013-06-13 15:32

MOT test number 307344063158

Notice Both front tyres starting to wear inner edges

CarCheck.co.uk page 3/10



report date: 2024-03-29

MOT test number

Result

Fail Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Notice Both front tyres starting to wear inner edges

MOT #4 2012-06-01 15:56 **MOT test number** 165413652155 Result ✓ Passed MOT #3 2012-06-01 09:48 375183052105 **MOT test number** Result × Failed Offside Front coil spring incomplete (2.4.C.1a) Fail Notice Bulb out in centre brake light

MOT #2	2011-06-20 13:51
MOT test number	695381671130
Result	✓ Passed
MOT #1	2010-06-25 11:21
MOT test number	610556870121
Result	./ Passed

CarCheck.co.uk page 4/10



report date: 2024-03-29

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

MW070JR

report date: 2024-03-29

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report here.

Plate changes

See in this check if this FIAT had different number plates.

More info >

More info >

CarCheck.co.uk page 7/10



report date: 2024-03-29

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >


CarCheck.co.uk page 8/10



MW070JR report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2007-06-28
Last registration	2021-01-20
Complete history	See info



Registration #1	2007-06-28	28 mi
Registration #2	2010-06-25	15.664 mi
Registration #3	2011-06-20	19.861 mi
Registration #4	2012-06-01	27.279 mi
Registration #5	2012-06-01	27.281 mi
Registration #6	2013-06-13	31.611 mi
Registration #7	2013-06-13	31.611 mi
Registration #8	2014-06-21	39.208 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		D.277 es

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-29

Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 10/

Number of axles 2
Engine number 4018117